

Damage Score Fraction of Historical Length Description Length within EF4 to EF5 Damage Area prior to disaster (ft) 0.00 10.00 0.00 Length within EF2 to EF4 Damage Area prior to disaster (ft) 0.00 5.00 0.00 Length within EF0 to EF2 Damage Area prior to disaster (ft) 0 0.00 2.00 0.00 Length Outside Damage Area prior to Disaster (ft) 2209 1.00 1.00 1.00

| LMI Benefit | | | | | |
|--|-----------------|-------|---------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 | |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 | |
| | | | I MI Score | 0.00 | |

| Health and Safety | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | |
| | | Hea | lth and Safety Score | 1.00 | |

| Long Term Recovery / Economic Revitalization Weighting | | | | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/ | Revitalization Score | 20.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Assessment Area

North 4th Street

Assessment Sub-Area N4A

Infrastructure Category

tegory Drainage

Exhibit Group E.4

| Proximity Analysis | | Function of | Walabilaa | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 286 | 0.13 | 10.00 | 1.29 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 286 | 0.13 | 5.00 | 0.65 |
| | | | Proximity Score | 1.94 |


Infrastructure Photographs

Damage Score

1.00









Infrastructure Rating Index (IRI)

45.02

Report Date: 3/10/2015 4:41:47 PM Page 36 of 70

Assessment Area North 4th Street


Assessment Sub-Area N4B

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 175 | | | |
| Total Drainage Channel Length (ft) | 9 | | | |
| Total Storm Sewer Structures (ea) | 3 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 175 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 175 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 3 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 183 | 0.99 | 5.00 | 4.97 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 183 | 0.99 | 2.00 | 1.99 |
| Age | | | | |
| More than 20-years | 63 | 0.36 | 10.00 | 3.60 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 112 | 0.64 | 1.00 | 0.64 |
| | | | Background Score | 16.20 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 1 | 0.50 | 0.50 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 0.50

Report Date: 3/10/2015 4:41:47 PM Page 37 of 70



Assessment Area North 4th Street
Assessment Sub-Area N4B
Infrastructure Category Drainage
Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | | |
|---|-------|-------------------|--------------|-------|--|
| Description | Value | Historical Length | Factor | Score | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 | |
| Length Outside Damage Area prior to Disaster (ft) | 175 | 1.00 | 1.00 | 1.00 | |
| | | | Damage Score | 1.00 | |

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 175 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | I MI Score | 5.00 |

Infrastructure Photographs

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | alth and Safety Score | 1.00 |













 Opportunity Score

 Project Description
 Score
 Factor
 Score

 No Projects Available
 0.00
 0.00
 0.00

Infrastructure Rating Index (IRI)

33.70

Report Date: 3/10/2015 4:41:47 PM Page 38 of 70

Assessment Area North 4th Street


Assessment Sub-Area N4C

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 336 | | | |
| Total Drainage Channel Length (ft) | 52 | | | |
| Total Storm Sewer Structures (ea) | 10 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 336 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 336 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 10 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 266 | 0.69 | 10.00 | 6.86 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 122 | 0.31 | 5.00 | 1.57 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 388 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 80 | 0.24 | 10.00 | 2.38 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 256 | 0.76 | 1.00 | 0.76 |
| | | | Background Score | 18.57 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 2 | 0.50 | 1.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 2 | 0.50 | 1.00 | | | | |
| D7 - Damage Structure | 1 | 0.50 | 0.50 | | | | |

Condition Score 2.50

Report Date: 3/10/2015 4:41:48 PM Page 39 of 70



Infrastructure Recovery and Implementation Plan
Infrastructure Assessment Form

| Assessment Area | North 4th Street |
|-------------------------|------------------|
| Assessment Sub-Area | N4C |
| Infrastructure Category | Drainage |
| Exhibit Group | E.4 |
| | |

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|--------------|-------|
| Description | Value | Historical Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 87 | 0.26 | 5.00 | 1.29 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 67 | 0.20 | 2.00 | 0.40 |
| Length Outside Damage Area prior to Disaster (ft) | 183 | 0.54 | 1.00 | 0.54 |
| | | | Damage Score | 2.24 |

| LMI Benefit | | | Mainhtina | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2021.05.3 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | alth and Safety Score | 1.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|------------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/I | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 183 | 0.54 | 10.00 | 5.45 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 5.45 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

29.76

Report Date: 3/10/2015 4:41:48 PM Page 40 of 70



City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Plaza Towers

Assessment Sub-Area P

Infrastructure Category Drainage

Exhibit Group E.4

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 158 | | | |
| Total Drainage Channel Length (ft) | 299 | | | |
| Total Storm Sewer Structures (ea) | 4 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 158 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 158 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 4 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 190 | 0.42 | 10.00 | 4.16 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 267 | 0.58 | 5.00 | 2.92 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 457 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 14.08 |

Key Map PT1 SW 19TH ST GREENS DRIVEWAY

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 4 | 0.50 | 2.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 3 | 0.50 | 1.50 |
| D4 - Insufficient armoring | 1 | 0.50 | 0.50 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 4 | 0.50 | 2.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 1 | 0.50 | 0.50 | | | | |

Condition Score 6.50

Report Date: 3/10/2015 4:41:48 PM



Assessment Sub-Area Infrastructure Category Exhibit Group

| Damage Score | | Fraction of | Mainhtin n | | |
|---|-------|-------------------|---------------------|-------|--|
| Description | Value | Historical Length | Weighting Factor | Score | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 9 | 0.06 | 5.00 | 0.28 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 149 | 0.94 | 2.00 | 1.89 | |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 | |
| | | | Damage Score | 2.17 | |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Description | Value | Score | Weighting Factor | Score |
|--|-------|-----------|----------------------|-------|
| Description | Value | | | |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| PT1: STORM SEWER IMPROVEMENTS AT COMMERCIAL PROPERTY, NW OF SW 19TH AND SA | 1.00 | 5.00 | 5.00 |
| IMPROVEMENTS TO STORM SEWER AT TERMINATION OF PENN LANE, BACKYARD OF LOTS | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 10.00 |

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|-----------------|-------|
| Description | Value | Total Length | Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

Infrastructure Photographs







Assessment Area

Plaza Towers

Drainage

E.4



Infrastructure Rating Index (IRI)

32.75

Date of Assessment

City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Plaza Towers

Assessment Sub-Area PT2

Infrastructure Category Drainage
Exhibit Group E.4

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 159 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Fotal Storm Sewer Structures (ea) | 1 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 159 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 159 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 1 | 1.00 | 5.00 | 5.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 159 | 1.00 | 10.00 | 10.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 110 | 0.69 | 5.00 | 3.46 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 49 | 0.31 | 2.00 | 0.62 |
| Age | | | | |
| More than 20-years | 159 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 32.08 |

| кеу шар | | | |
|---------|----------------|--|--|
| NORTH | GIPPO SW111 | THIST | SWITH ST OF CO. |
| | SW 12 | THIST THE THE THE THE THE THE THE THE THE TH | RIDGEWAY DR. PRINCE WAY DR. PRINCE W |
| | S SANTA FE AVE | PT2 | SW14THST |
| | | | LAKEVIEW DR. |
| | SW 16 | | ERIC CIR |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 2 | 0.50 | 1.00 | D8 - Apparent previous maintenance | 1 | 0.50 | 0.50 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 1 | 0.50 | 0.50 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 3 | 0.50 | 1.50 | D12 - evidence of ponding | 54 | 0.50 | 27.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 30.50

Report Date: 3/10/2015 4:41:49 PM



Assessment Area Plaza Towers
Assessment Sub-Area PT2
Infrastructure Category Drainage
Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|--------------|-------|
| Description | Value | Historical Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 159 | 1.00 | 10.00 | 10.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 10.00 |

| Proximity Analysis | | Footbook | W. S. L.C. | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 159 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

Infrastructure Photographs

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | alth and Safety Score | 1.00 |





| | | Tice | initi and Salety Score | 1.00 |
|--|-------|-----------|------------------------|-------|
| Long Term Recovery / Economic Revitalization Description | Value | Score | Weighting Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/ | Revitalization Score | 20.00 |





| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

 Opportunity Score

 Project Description
 Score
 Weighting Factor
 Score

 SUB-AREA PT2: CONSTRUCTION OF NEW PUBLIC STORM SEWER THROUGHOUT AREA
 1.00
 5.00
 5.00

 IMPROVEMENTS TO STORM SEWER AT TERMINATION OF PENN LANE, BACKYARD OF LOTS
 1.00
 5.00
 5.00

 Opportunity Score
 10.00

Infrastructure Rating Index (IRI)

118.58

Report Date: 3/10/2015 4:41:49 PM Page 44 of 70



Date of Assessment

City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Plaza Towers

PT3 **Assessment Sub-Area**

Infrastructure Category Drainage

> **Exhibit Group** E.4

Assessment Data Description Value Assessment By J.Cotton / A.Hartman 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 1567 | | | |
| Total Drainage Channel Length (ft) | 1389 | | | |
| Total Storm Sewer Structures (ea) | 20 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 738 | 0.47 | 5.00 | 2.35 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 828 | 0.53 | 1.00 | 0.53 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 1567 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 4 | 0.20 | 5.00 | 1.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 16 | 0.80 | 2.00 | 1.60 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 2119 | 0.72 | 10.00 | 7.17 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 837 | 0.28 | 5.00 | 1.42 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 300 | 0.10 | 5.00 | 0.51 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 2656 | 0.90 | 2.00 | 1.80 |
| Age | | | | |
| More than 20-years | 718 | 0.46 | 10.00 | 4.58 |
| 15 to 20-years | 791 | 0.50 | 5.00 | 2.52 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 57 | 0.04 | 1.00 | 0.04 |
| | | | Background Score | 25.51 |

| The same state of the same sta | |
|--|--|
| | |
| NORTH CIPCLESW 11TH STP COLOR OF COLOR | Ar S |
| COCOCO SW.12TH'ST.P. | ANAMA'S ANAMA'S ANAMA'S ANAMA'S SANAMA'S SANAMA' |
| SW-12TH-ST | S JANEWAY AVE. |
| SW 12TH ST POLICY SW 12TH ST POLICY SW 13TH ST P | AVE SW 14TH S |
| | |
| | Manage St. |
| | |
| S S S S S S S S S S S S S S S S S S S | ARENIA |
| S. S. SANTALE MANAGER AND STANDARD STAN | |
| | 11 19 10 cm |
| | SAN BLVD |
| | MAX MORGAN BLVD |
| SW 149TH ST SW 19TH ST | SW 19TH ST |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 2 | 0.50 | 1.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 9 | 0.50 | 4.50 |
| D4 - Insufficient armoring | 6 | 0.50 | 3.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 17 | 0.50 | 8.50 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 1 | 0.50 | 0.50 | | | | |

Condition Score 17.50

Report Date: 3/10/2015 4:41:50 PM Page 45 of 70



Assessment Area Plaza Towers
Assessment Sub-Area PT3
Infrastructure Category Drainage
Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|--------------|-------|
| Description | Value | Historical Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 59 | 0.04 | 10.00 | 0.38 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1069 | 0.68 | 5.00 | 3.41 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 439 | 0.28 | 2.00 | 0.56 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 4.35 |

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|-----------------|-------|
| Description | Value | Total Length | Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 1567 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

Infrastructure Photographs

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|---------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | He | alth and Safety Scor | re 1.00 |





| | | Tice | Health and Salety Score | |
|--|-------|-----------|-------------------------|-------|
| Long Term Recovery / Economic Revitalization Description | Value | Score | Weighting Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/ | Revitalization Score | 20.00 |





| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q18: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 | |
| | | | Sustainability Score | 5.00 | |

Opportunity Score Project Description Score 5.00 5.00 LAKE EDGE RESTORATION/ BEAUTIFIUCATION/SCREEN RESIDENTIAL FROM COMMERCIAL 1.00 SUB-AREA PT3: CONSTRUCTION OF NEW PUBLIC STORM SEWER AS REQUIRED 1.00 5.00 5.00 5.00 IMPROVEMENTS TO STORM SEWER AT TERMINATION OF PENN LANE, BACKYARD OF LOTS 1.00 5.00 DRAINAGE CHANNEL INPROVEMENTS NORTH OF POND, NEW RCB STRUCTURE AT SW 11TH 5.00 5.00 1.00 Opportunity Score 20.00

Infrastructure Rating Index (IRI)

103.36

Report Date: 3/10/2015 4:41:50 PM Page 46 of 70



City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Plaza Towers

Assessment Sub-Area P

Infrastructure Category Drainage

Exhibit Group E.4


 Assessment Data

 Description
 Value

 Assessment By
 J.Cotton / A.Hartman

 Date of Assessment
 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 0 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 0 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 0.00 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 7 | 0.50 | 3.50 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 3.50

Report Date: 3/10/2015 4:41:51 PM



Assessment Area Plaza Towers **Assessment Sub-Area Infrastructure Category** Drainage **Exhibit Group** E.4

| Damage Score | | Fraction of | Mainháin n | | |
|---|-------|-------------------|---------------------|-------|--|
| Description | Value | Historical Length | Weighting Factor | Score | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 | |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 | |
| | | | Damage Score | 0.00 | |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |


Infrastructure Photographs

| Health and Safety | Weighting | | | |
|--|-----------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | alth and Safety Score | 1.00 |













Infrastructure Rating Index (IRI)



1.00

Sustainability

SUB-AREA PT4: PUBLIC STORM SEWER IMPROVEMENTS AS REQUIRED

Report Date: 3/10/2015 4:41:51 PM Page 48 of 70

5.00

5.00

5.00 Opportunity Score

Assessment Area Plaza Towers

Assessment Sub-Area PT5

Infrastructure Category Drainage

Exhibit Group E.4

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 1569 | | | |
| Total Drainage Channel Length (ft) | 2217 | | | |
| Total Storm Sewer Structures (ea) | 20 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 1569 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 1569 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 20 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 3786 | 1.00 | 10.00 | 10.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 3786 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 1541 | 0.98 | 10.00 | 9.82 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 28 | 0.02 | 1.00 | 0.02 |
| | | | Background Score | 26.84 |

Key Map SW 4TH ST NORTH SW 6TH ST SW8TH ST PT5 SW 10TH ST

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 1 | 0.50 | 0.50 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 4 | 0.50 | 2.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 1 | 0.50 | 0.50 |
| D4 - Insufficient armoring | 1 | 0.50 | 0.50 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 1 | 0.50 | 0.50 | D12 - evidence of ponding | 44 | 0.50 | 22.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 2 | 0.50 | 1.00 | | | | |

Condition Score 27.00

Report Date: 3/10/2015 4:41:51 PM



Infrastructure Recovery and Implementation Plan
Infrastructure Assessment Form

Assessment Area Plaza Towers PT5 **Assessment Sub-Area** Drainage Infrastructure Category Exhibit Group E.4

| Damage Score | | Fraction of | Walakiaa | Score | |
|---|-------|-------------------|---------------------|-------|--|
| Description | Value | Historical Length | Weighting Factor | | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 793 | 0.51 | 2.00 | 1.01 | |
| Length Outside Damage Area prior to Disaster (ft) | 777 | 0.50 | 1.00 | 0.50 | |
| | | | Damage Score | 1.51 | |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |

| Health and Safety | n and Safety Weighting | | | | | | |
|--|------------------------|-------|-----------------------|-------|--|--|--|
| Description | Value | Score | Factor | Score | | | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | | | |
| | | Hea | alth and Safety Score | 1.00 | | | |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/ | Revitalization Score | 20.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

| Opportunity Score | | Waighting | |
|--|-------|---------------------|-------|
| Project Description | Score | Weighting Factor | Score |
| SUB-AREA PT5: CONSTRUCTION OF NEW PUBLIC STORM SEWER AS REQUIRED | 1.00 | 5.00 | 5.00 |
| PT5: DRAINAGE IMPROVEMENTS, TERMINATION OF SW 8TH STREET | 1.00 | 5.00 | 5.00 |
| PT5: CONCRETE CHANNEL REPLACEMENT | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 15 00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 793 | 0.51 | 10.00 | 5.05 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 5.05 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

101.40

Report Date: 3/10/2015 4:41:52 PM Page 50 of 70

Assessment Area Plaza Towers


Assessment Sub-Area PT6

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 558 | | | |
| Total Drainage Channel Length (ft) | 426 | | | |
| Total Storm Sewer Structures (ea) | 2 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 558 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 558 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 1 | 0.50 | 5.00 | 2.50 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 1 | 0.50 | 2.00 | 1.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 983 | 1.00 | 10.00 | 9.99 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 532 | 0.54 | 5.00 | 2.70 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 452 | 0.46 | 2.00 | 0.92 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 555 | 0.99 | 2.00 | 1.99 |
| Unknown | 3 | 0.01 | 1.00 | 0.01 |
| | | | Background Score | 22.11 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 8 | 0.50 | 4.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 1 | 0.50 | 0.50 | | | | |

Condition Score 4.50

Report Date: 3/10/2015 4:41:52 PM Page 51 of 70



Assessment Sub-Area Infrastructure Category Exhibit Group

| Damage Score | | Fraction of | Wainkiinn | |
|---|-------|-------------------|---------------------|-------|
| Description | Value | Historical Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3 | 0.01 | 2.00 | 0.01 |
| Length Outside Damage Area prior to Disaster (ft) | 555 | 0.99 | 1.00 | 0.99 |
| | | | Damage Score | 1.01 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |


| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

Infrastructure Photographs







Assessment Area

Plaza Towers

PT6

E.4

Drainage



Infrastructure Rating Index (IRI)

27.61

Assessment Area Santa Fe Avenue

Assessment Sub-Area

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Storm Sewer Line Length (ft) | 1037 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 15 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 1037 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 1037 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 15 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 1037 | 1.00 | 10.00 | 10.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 1037 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 754 | 0.73 | 5.00 | 3.64 |
| 10 to 15-years | 117 | 0.11 | 4.00 | 0.45 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 166 | 0.16 | 1.00 | 0.16 |
| | | | Background Score | 21.25 |

| кеу шар | |
|--|-------------|
| SSW 149TH ST S | SW 19TH ST |
| NORTH WORTH ST ST COURSE COURSE COU | GREENS |
| | S GREENS DR |
| TOTAL THE PROPERTY OF THE STATE | |
| ODDOOD BRAKE | GREENS DR |
| SW 21ST ST SW 21ST SW 21ST ST SW 21ST SW | |
| | Series DR |
| | |
| ODD POPOLATION POPOLATION POPULATION POPULAT | S GREENS DR |
| 6 170 100 170 170 170 170 170 170 170 170 | |
| | |
| | |
| SW 2674 ST SOLD OF THE STATE OF | |
| | |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 0.00

Report Date: 3/10/2015 4:41:53 PM Page 53 of 70

Key Map



Damage Score Fraction of Historical Length Description Length within EF4 to EF5 Damage Area prior to disaster (ft) 0.00 10.00 0.00 Length within EF2 to EF4 Damage Area prior to disaster (ft) 0.00 5.00 0.00 Length within EF0 to EF2 Damage Area prior to disaster (ft) 124 0.12 2.00 0.24 Length Outside Damage Area prior to Disaster (ft) 913 0.88 1.00 0.88 Damage Score 1.12

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2022.06.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | |
| | | Hea | Ith and Safety Score | 1.00 | |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Assessment Area

Santa Fe Avenue

Assessment Sub-Area

Infrastructure Category

Drainage


Exhibit Group E.4

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|-----------------|-------|
| Description | Value | Total Length | Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 913 | 0.88 | 10.00 | 8.80 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 8.80 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

32.17

Report Date: 3/10/2015 4:41:53 PM Page 54 of 70

Southgate Assessment Area SG3 **Assessment Sub-Area** Infrastructure Category Drainage

Exhibit Group E.4

Assessment Data Description Value Assessment By J.Cotton / A.Hartman 3/10/2015

Key Map

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 925 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 12 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 925 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 925 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 12 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 19 | 0.02 | 10.00 | 0.21 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 925 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 925 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 17.21 |

| NORTH | | | |
|--------|--|-----------|-----------|
| MATATT | | | |
| | | | |
| | | | SW 1ST ST |
| | | | SW 2ND ST |
| | | SG3 | SW3RD ST |
| | | | SW4TH P |
| DR | | SW 4TH ST | SW4IHPI |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 79 | 0.50 | 39.50 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 6 | 0.50 | 3.00 | | | | |

Condition Score 42.50

Report Date: 3/10/2015 4:41:53 PM

Date of Assessment



Southgate Assessment Area SG3 **Assessment Sub-Area** Drainage Infrastructure Category Exhibit Group E.4

| Damage Score | | Fraction of | Wainkinn | |
|---|-------|-------------------|---------------------|-------|
| Description | Value | Historical Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 623 | 0.67 | 1.00 | 0.67 |
| | | | Domono Sooro | 0.67 |

| Damage Score | 0.67 |
|--------------|------|
|--------------|------|

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.02.3 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | I MI Score | 5 00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | Ith and Safety Score | 1.00 |

| Description | Value | Score | Weighting Factor | Score |
|--|-------|-----------|----------------------|-------|
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 15.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|---|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SG3: RECONSTRUCTION OF ALL PUBLIC STORM SEWER | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

86.38

Assessment Area Southgate
Assessment Sub-Area SG4

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 128 | | | |
| Total Drainage Channel Length (ft) | 1160 | | | |
| Total Storm Sewer Structures (ea) | 8 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 128 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 128 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 8 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 1288 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 128 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 17.00 |

| Key Map | | |
|---------|-----|--|
| NORTH | | |
| | | |
| | | |
| | | |
| | SG4 | |
| | | |
| 3 | | |
| | | |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 22 | 0.50 | 11.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 11 | 0.50 | 5.50 | D12 - evidence of ponding | 64 | 0.50 | 32.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 48.50

Report Date: 3/10/2015 4:41:54 PM Page 57 of 70



Assessment Area Southgate
Assessment Sub-Area SG4
Infrastructure Category Drainage
Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|--------------|-------|
| Description | Value | Historical Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 34 | 0.27 | 1.00 | 0.27 |
| | | | Damage Score | 0.27 |

| Proximity Analysis | | Function of | Wainbin | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.02.3 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | LMI Score | 5.00 |

Infrastructure Photographs

| Health and Safety Weighting | | | | | | | |
|--|-------|-------|-----------------------|-------|--|--|--|
| Description | Value | Score | Factor | Score | | | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | | | |
| | | Hea | alth and Safety Score | 1.00 | | | |





| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 15.00 |

Sustainability

Q18: Opportunity for introduction of sustainable design concepts







Value

Score

0.00

Weighting Factor

5.00

0.00

Infrastructure Rating Index (IRI)

91.77

Report Date: 3/10/2015 4:41:55 PM Page 58 of 70

Assessment Area Southgate
Assessment Sub-Area SG5

Infrastructure Category Drainage

Exhibit Group E.4

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 300 | | | |
| Total Drainage Channel Length (ft) | 20 | | | |
| Total Storm Sewer Structures (ea) | 2 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 300 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 300 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 2 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 12 | 0.04 | 10.00 | 0.38 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 319 | 1.00 | 2.00 | 1.99 |
| Age | | | | |
| More than 20-years | 300 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 17.37 |

Key Map NORTH SG5 SW 4TH ST S SANTA FE AVE

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 1 | 0.50 | 0.50 | D11 - exposed reinforcing steel | 1 | 0.50 | 0.50 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 1 | 0.50 | 0.50 | | | _ | |

Condition Score 1.50

Report Date: 3/10/2015 4:41:55 PM



Assessment Area Southgate Assessment Sub-Area SG5 **Infrastructure Category** Drainage E.4 **Exhibit Group**

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|--------------|-------|
| Description | Value | Historical Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 300 | 1.00 | 1.00 | 1.00 |
| | | | Damage Score | 1.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.02.3 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | I MI Score | 5.00 |

Infrastructure Photographs

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 |
| | | Hea | alth and Safety Score | 1.00 |





Weighting Factor

5.00

Sustainability Score

0.00

0.00





Sustainability

Q18: Opportunity for introduction of sustainable design concepts

Description







Opportunity Score Weighting Factor **Project Description** Score SG5: RECONSTRUCTION OF ALL PUBLIC STORM SEWER 1.00 5.00 5.00 Opportunity Score 5.00

Value

No

Score

0.00

Infrastructure Rating Index (IRI)

45.87

Date of Assessment

Assessment Area Southmoor
Assessment Sub-Area SM2

Infrastructure Category Drainage
Exhibit Group E.4

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 745 | | | |
| Total Drainage Channel Length (ft) | 645 | | | |
| Total Storm Sewer Structures (ea) | 13 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 745 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 745 | 1.00 | 2.00 | 2.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 13 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 1390 | 1.00 | 10.00 | 10.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 1390 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 744 | 1.00 | 10.00 | 9.99 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 1 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 26.99 |

| NORTH SWETHST |
|---|

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 42 | 0.50 | 21.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | _ | |

Condition Score 21.00

Report Date: 3/10/2015 4:41:56 PM Page 61 of 70



Assessment Area Southmoor SM2 **Assessment Sub-Area** Drainage Infrastructure Category **Exhibit Group** E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|---------------------|-------|
| Description | Value | Historical Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 143 | 0.19 | 10.00 | 1.92 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 29 | 0.04 | 5.00 | 0.19 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 250 | 0.34 | 2.00 | 0.67 |
| Length Outside Damage Area prior to Disaster (ft) | 323 | 0.43 | 1.00 | 0.43 |
| | | | Damage Score | 3.22 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |

| Health and Safety | ealth and Safety Weighting | | | | | |
|--|----------------------------|-------|-----------------------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | | |
| | | Hea | alth and Safety Score | 1.00 | | |

| Long Term Recovery / Economic Revitalization | | | Weighting | | |
|--|-------|-----------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q13: Opportunity to improve community asethetic | Yes | 1.00 | 5.00 | 5.00 | |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q15: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q16: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| Q17: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| | | Recovery/ | Revitalization Score | 25.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

| Opportunity Score | | Weighting | |
|--|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SUB-AREA SM2: CONSTRUCTION OF NEW PUBLIC STORM SEWER THROUGHOUT SUB-AREA | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|-----------------|-------|
| Description | Value | Total Length | Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 324 | 0.43 | 10.00 | 4.35 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 324 | 0.43 | 5.00 | 2.17 |
| | | | Proximity Score | 6.52 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

93.73

Assessment Area Tower Drive District


Assessment Sub-Area TD3

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 0 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 0 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 0.00 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 2 | 0.50 | 1.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 1.00

Report Date: 3/10/2015 4:41:56 PM Page 63 of 70

Assessment Area Tower Drive District

Assessment Sub-Area TD3

Infrastructure Category Drai

Drainage

Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|---------------------|-------|
| Description | Value | Historical Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | | |
|--|-------|-----------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 | |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery/ | Revitalization Score | 0.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

| Proximity Analysis | | Fraction of | Weighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

1.00

Report Date: 3/10/2015 4:41:57 PM Page 64 of 70

City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Tower Drive

Assessment Sub-Area TW1

Infrastructure Category

Exhibit Group E.4

Drainage

Assessment Data

Description Value

Assessment By J.Cotton / A.Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 1553 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 21 | | | |
| Line Size | | | | |
| RCB | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 36-in equivalent or greater (ft) | 411 | 0.26 | 10.00 | 2.65 |
| Diameter 18-in to 30-in equivalent (ft) | 269 | 0.17 | 5.00 | 0.87 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 873 | 0.56 | 1.00 | 0.56 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 680 | 0.44 | 5.00 | 2.19 |
| Length of Unknown (ft) | 873 | 0.56 | 2.00 | 1.12 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 5 | 0.24 | 5.00 | 1.19 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 16 | 0.76 | 2.00 | 1.52 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 1553 | 1.00 | 10.00 | 10.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 105 | 0.07 | 5.00 | 0.34 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 1449 | 0.93 | 2.00 | 1.87 |
| Age | | | | |
| More than 20-years | 520 | 0.33 | 10.00 | 3.35 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 1 | 0.00 | 2.00 | 0.00 |
| Unknown | 1032 | 0.66 | 1.00 | 0.66 |
| | | | Background Score | 26.32 |

| кеу мар | | | |
|--|--|--|--|
| 4TH ST SW4TH S | SW4TH ST | og di la se | 4TH ST े व व व व व व व व व व व व व व व व व व |
| | SW 4TH ST | TOWERCR | Des to see a |
| NORTH CLASSIFICATION OF THE STATE OF THE STA | SW5TH ST | | MOOR CIT SERVICE AND SERVICE A |
| STOCKETHSTAND STOCKETHSTAND | SW:6TH ST | SE 6TH ST(s) | EASTMOOR CT. TO SELVE THE SOLUTION OF STREET O |
| E EMPERICADA 7 | | RIDGE RD | SE STHIST |
| S SW 7TH ST | SW 8TH STO | | REPARENCE CONTRACTOR STATE OF THE STATE OF T |
| SW/8TH/STID BILL WARRY DR | SW.9TH.ST | MADISON | PRISE 10TH STORY SELITH STORY |
| a SW.9TH STi-0 | SW-107H-ST | MADISON A CE DR MADISON CT 2 | DECOMPTED SELECTION OF THE SECOND SECOND SELECTION OF THE SECOND SECOND SECOND SECOND SELECTION OF THE SECOND SECON |
| TOTAL CHARLES WAS A STATE OF THE STATE OF TH | © SW.11THST | SE 10TH SE SE SE | 3300 SE 12TH STOOD DOOD TO |
| CORD ZICOCOCCOCIO | BROADURE ASSESSED ASS | 0.000 | CAN CAR PROPERTY OF THE PROPER |
| ESW.12TH.ST | SW 13TH ST | CLOVER OF THE STATE OF THE STAT | GOOGSE 1374:ST |
| SW 13TH ST | SW-14TH-ST O | TURILE LAKER | W DOD STATH STORY OF THE STORY |
| Z Course Cha L | SW.15TH ST | SE PERS DR 22 | 15TH ST CONSCIONATION CONTRACTOR |
| S TELEPHONE BY STANFORMS STELEPHONE BY STANFORMS STELE | SW(16TH/ST | CONTROL OF THE PARTY OF THE PAR | |
| E E P | ************************************** | THE STATE OF THE S | |
| 5m | | The second secon | |
| | | Selection of the select | |
| | | | |
| SW 19TH ST | | | |
| | | | W.S. W. S. W. C. I. C. I |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 1 | 0.50 | 0.50 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | _ | |

Condition Score 0.50

Report Date: 3/10/2015 4:41:57 PM



Assessment Area Tower Drive TW1 **Assessment Sub-Area** Infrastructure Category Drainage **Exhibit Group** E.4

| Damage Score | | Fraction of | Weighting | |
|---|-------|-------------------|---------------------|-------|
| Description | Value | Historical Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 164 | 0.11 | 10.00 | 1.06 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 516 | 0.33 | 5.00 | 1.66 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 540 | 0.35 | 2.00 | 0.70 |
| Length Outside Damage Area prior to Disaster (ft) | 333 | 0.21 | 1.00 | 0.21 |
| | | | Damage Score | 3.63 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 35 | 0.02 | 10.00 | 0.23 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.23 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q11: Improvements would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |

Infrastructure Photographs

| Health and Safety | alth and Safety Weighting | | | | | |
|--|---------------------------|-------|-----------------------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | | |
| | | Hea | alth and Safety Score | 1.00 | | |



| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | |
|--|-------|-------|-----------------------|-------|--|
| | | Hea | alth and Safety Score | 1.00 | |
| Long Term Recovery / Economic Revitalization | | | Weighting | | |
| Description | Value | Score | Factor | Score | |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 | |





No

0.00

5.00

0.00







| Opportunity Score | re Weighting | | | |
|-----------------------|-----------------|--------|-------|--|
| Project Description | Score | Factor | Score | |
| No Projects Available | 0.00 | 0.00 | 0.00 | |

Infrastructure Rating Index (IRI)

31.67

Report Date: 3/10/2015 4:41:57 PM Page 66 of 70

Assessment Area Warren Theater

Assessment Sub-Area WT1

Infrastructure Category Drainage

Exhibit Group E.4

| Assessment Data | |
|--------------------|----------------------|
| Description | Value |
| Assessment By | J.Cotton / A.Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 5904 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 36 | | | |
| Line Size | | | | |
| RCB | 1184 | 0.20 | 10.00 | 2.01 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 5904 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Unknown (ft) | 4720 | 0.80 | 2.00 | 1.60 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 36 | 1.00 | 2.00 | 2.00 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 5315 | 0.90 | 10.00 | 9.00 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 589 | 0.10 | 5.00 | 0.50 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 0 | 0.00 | 5.00 | 0.00 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 5904 | 1.00 | 2.00 | 2.00 |
| Age | | | | |
| More than 20-years | 1827 | 0.31 | 10.00 | 3.09 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 4077 | 0.69 | 2.00 | 1.38 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 22.58 |

| NORTH SWATH ST | SW 4TH ST | SW 4TH ST * SW 4TH ST | SE 4TH ST |
|--|-------------------------------------|---|-----------|
| | | SW STHIST OF | |
| SW 6TH ST SW 6TH ST KINGS MANOR DR | S CLASSEN AVE SW 6TH ST | SHOWN | 6 |
| STEEPHONE STEEPH | SWYTH ST. JOSSENAW BILL WARRENOP | SW 7TH ST | |
| COLUDAD PEDE | | S. BROADWAY AVE | |
| SW 9TH ST COLOR SW 9TH ST COLO | WT1 | SW10TH ST | |
| Clonflyon Codescoses D Little River Cir. Codescoses D Little | SW 11TH ST | O SW 11THST OF | |

| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 0 | 0.50 | 0.00 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 0.00

Report Date: 3/10/2015 4:41:58 PM Page 67 of 70



| Damage Score | | Fraction of | Malakiaa | Score | |
|---|-------|-------------------|---------------------|-------|--|
| Description | Value | Historical Length | Weighting Factor | | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1959 | 0.33 | 5.00 | 1.66 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3945 | 0.67 | 2.00 | 1.34 | |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 | |
| | | | Damage Score | 3.00 | |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | LMI Score | 15.00 |

| Health and Safety | | | Weighting | | |
|--|-------|-------|-----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q12: Opportunity to harden infrastructure against future disasters | Yes | 1.00 | 1.00 | 1.00 | |
| | | Hea | alth and Safety Score | 1.00 | |

| Long Term Recovery / Economic Revitalization | Value | C | Weighting | 0 |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q18: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Exhibit Group E.4 Fraction of Total Length Value

5792

5792

Assessment Area

0.98

0.98

Assessment Sub-Area

Infrastructure Category

Warren Theater

10.00

5.00

Proximity Score

9.81

4.91

14.72

WT1

Drainage

Infrastructure Photographs

Length within 0.25-mi of Critical User (ft)

Length within 0.25-mi of Emergency Response Facility (ft)

Proximity Analysis









Infrastructure Rating Index (IRI)

56.29

Report Date: 3/10/2015 4:41:58 PM Page 68 of 70

Assessment Area Warren Theater

Assessment Sub-Area WT3


Infrastructure Category

Exhibit Group E.4

Drainage

Assessment Data Description Value Assessment By J.Cotton / A.Hartman Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-------------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Storm Sewer Line Length (ft) | 3003 | | | |
| Total Drainage Channel Length (ft) | 0 | | | |
| Total Storm Sewer Structures (ea) | 18 | | | |
| Line Size | | | | |
| RCB | 1625 | 0.54 | 10.00 | 5.41 |
| Diameter 36-in equivalent or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 18-in to 30-in equivalent (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter Less than 18-in equivalent (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Diameter Unknown (ft) | 3003 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Corrugated Metal (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of Concrete (ft) | 140 | 0.05 | 5.00 | 0.23 |
| Length of Unknown (ft) | 1239 | 0.41 | 2.00 | 0.83 |
| Corrosion | | | | |
| Structures within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Structures within "Medium Concrete Corrosion Potential" (ea) | 2 | 0.11 | 5.00 | 0.56 |
| Structures within "Low Concrete Corrosion Potential" (ea) | 16 | 0.89 | 2.00 | 1.78 |
| Drainage Infrastructure within "High Steel Corrosion Potential" (ea) | 418 | 0.14 | 10.00 | 1.39 |
| Drainage Infrastructure within "Medium Steel Corrosion Potential" (ea) | 2585 | 0.86 | 5.00 | 4.30 |
| Drainage Infrastructure within "Low Steel Corrosion Potential" (ea) | 0 | 0.00 | 2.00 | 0.00 |
| Drainage Infrastructure within "High Concrete Corrosion Potential" (ea) | 0 | 0.00 | 10.00 | 0.00 |
| Drainage Infrastructure within "Medium Concrete Corrosion Potential" (ea) | 219 | 0.07 | 5.00 | 0.36 |
| Drainage Infrastructure within "Low Concrete Corrosion Potential" (ea) | 2785 | 0.93 | 2.00 | 1.85 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 3003 | 1.00 | 2.00 | 2.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 19.72 |



| Condition Analysis | | Weighting | | | | Weighting | |
|---|----------|-----------|-------|------------------------------------|----------|-----------|-------|
| Description | Quantity | Factor | Score | Description | Quantity | Factor | Score |
| D1 - Grate or hood damage | 0 | 0.50 | 0.00 | D8 - Apparent previous maintenance | 0 | 0.50 | 0.00 |
| D2 - Improper inlet elevation | 0 | 0.50 | 0.00 | D9 - Channel maintenance required | 0 | 0.50 | 0.00 |
| D3 - Improper inlet placement | 0 | 0.50 | 0.00 | D10 - Channel damage from erosion | 0 | 0.50 | 0.00 |
| D4 - Insufficient armoring | 0 | 0.50 | 0.00 | D11 - exposed reinforcing steel | 0 | 0.50 | 0.00 |
| D5 - Indications of insufficient capacity | 0 | 0.50 | 0.00 | D12 - evidence of ponding | 1 | 0.50 | 0.50 |
| D6 - Brick Structure | 0 | 0.50 | 0.00 | | | | |
| D7 - Damage Structure | 0 | 0.50 | 0.00 | | | | |

Condition Score 0.50

Report Date: 3/10/2015 4:41:59 PM



Assessment Area Warren Theater

Assessment Sub-Area WT3

Infrastructure Category Drainage

Exhibit Group E.4

| Damage Score | | Fraction of | Weighting | | |
|---|-------|-------------------|--------------|-------|--|
| Description | Value | Historical Length | Factor | Score | |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 | |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 | |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 454 | 0.15 | 2.00 | 0.30 | |
| Length Outside Damage Area prior to Disaster (ft) | 2549 | 0.85 | 1.00 | 0.85 | |
| | | | Damage Score | 1.15 | |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical User (ft) | 31 | 0.01 | 10.00 | 0.10 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 31 | 0.01 | 5.00 | 0.05 |
| | | | Proximity Score | 0.15 |

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q10: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 |
| Q11: Improvements would benefit LMI Census Block Group | Yes | 1.00 | 5.00 | 5.00 |
| | | | I MI Score | 15.00 |

Infrastructure Photographs

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q12: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |






| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q13: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q14: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q15: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q16: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q17: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 0.00 |







 Opportunity Score

 Project Description
 Score
 Factor
 Score

 No Projects Available
 0.00
 0.00
 0.00

Infrastructure Rating Index (IRI)

36.52

Report Date: 3/10/2015 4:41:59 PM Page 70 of 70

Assessment Area Bryant Avenue

Assessment Sub-Area BA1

Infrastructure Category Water Distribution

Exhibit Group E.5

| As | sessment Data | |
|----|---------------|--|
| | | |

Value

Assessment By J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 1280 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 1264 | 0.99 | 10.00 | 9.88 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 16 | 0.01 | 1.00 | 0.01 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 1280 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 10.00 | 0.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 1280 | 1.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 1217 | 0.95 | 10.00 | 9.51 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 63 | 0.05 | 1.00 | 0.05 |
| | | | Background Score | 24.44 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 1280 | 1.00 | 1.00 | 1.00 |
| | | | Damage Score | 1.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 1022 | 0.80 | 10.00 | 7.98 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 7.98 |

Key Map 12-IN 00000000000 8900 00 6-N SE-12TH STOP COCCSE 13TH STOG-IN 6-IN SE 14TH ST enopeopopopop, 6 SE 15TH ST 6 IN 2 24000 DOGCO 6-INC SE 16TH ST

| Condition Analysis | | Weighting Factor | | | |
|--|----------|---------------------|-------|--|--|
| Description | Quantity | racioi | Score | | |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 | | |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | | |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 | | |
| | С | ondition Score | 0.00 | | |

Report Date: 3/10/2015 4:57:52 PM Page 1 of 62

Assessment Area Bryant Avenue
Assessment Sub-Area BA1

Infrastructure Category Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.07.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|----------|-------------------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | Recovery/Revitalization Score | |


| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs

LMI Score 0.00





Infrastructure Rating Index (IRI)

33.43

Report Date: 3/10/2015 4:57:53 PM Page 2 of 62

Assessment Area Bryant Avenue

Assessment Sub-Area BA2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value

Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Water Line Length (ft) | 1823 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 1425 | 0.78 | 10.00 | 7.82 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 398 | 0.22 | 1.00 | 0.22 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 1823 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 10.00 | 0.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 1823 | 1.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 436 | 0.24 | 10.00 | 2.39 |
| 15 to 20-years | 1364 | 0.75 | 5.00 | 3.74 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 23 | 0.01 | 1.00 | 0.01 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 44 | 0.02 | 5.00 | 0.12 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 900 | 0.49 | 2.00 | 0.99 |
| Length Outside Damage Area prior to Disaster (ft) | 879 | 0.48 | 1.00 | 0.48 |
| | | | Damage Score | 1.59 |

Background Score 19.18

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Provimity Score | 0.00 |

Key Map NE 1ST ST 04 EMAIN ST SE 4TH ST ₹ E

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | C | ondition Score | 0.00 |

Report Date: 3/10/2015 4:57:53 PM Page 3 of 62

Bryant Avenue

Assessment Sub-Area BA2

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.06.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Mainhtina | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | | | |
|-----------------------|-------|-----------|-------|--|--|
| Project Description | Score | Factor | Score | | |
| No Projects Available | 0.00 | 0.00 | 0.00 | | |

Infrastructure Photographs

LMI Score 0.00







Assessment Area Broadway Avenue

Assessment Sub-Area BR1

Infrastructure Category Water Distribution

Exhibit Group E.5

| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-----------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 5198 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 51 | 0.01 | 10.00 | 0.10 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 5147 | 0.99 | 1.00 | 0.99 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 5198 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 5198 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 3753 | 0.72 | 10.00 | 7.22 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 1446 | 0.28 | 1.00 | 0.28 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 172 | 0.03 | 10.00 | 0.33 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 989 | 0.19 | 5.00 | 0.95 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 1517 | 0.29 | 2.00 | 0.58 |
| Length Outside Damage Area prior to Disaster (ft) | 1353 | 0.26 | 1.00 | 0.26 |
| | | | Damage Score | 2.13 |

Background Score 23.59

| Proximity Analysis | | Function of | Mainhain n | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | Weighting Factor | | | |
|--|---------------------|-----------------|-------|--|
| Description | Quantity | | Score | |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 | |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 | |
| | | Condition Score | 0.00 | |

Report Date: 3/10/2015 4:57:54 PM Page 5 of 62

Broadway Avenue

Assessment Sub-Area BR1

Infrastructure Category Wa

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | afety Weighting | | | | |
|--|-----------------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | |
| | | Hea | lth and Safety Score | 0.00 | |

| Long Term Recovery / Economic Revitalization | | | Mainhtinn | | |
|--|-------|----------|-------------------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | Recovery/Revitalization Score | | |

| Sustainability | , Weighting | | | | |
|--|----------------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | | |
|-----------------------|-------|-----------|-------|--|
| Project Description | Score | Factor | Score | |
| No Projects Available | 0.00 | 0.00 | 0.00 | |

Infrastructure Photographs

LMI Score 0.00









Assessment Area Baer's Westmoore

Assessment Sub-Area BW2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| otal Water Line Length (ft) | 11992 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 153 | 0.01 | 10.00 | 0.13 |
| Diameter 8-in to 12-in (ft) | 2681 | 0.22 | 5.00 | 1.12 |
| Diameter 4-in to 6-in (ft) | 9158 | 0.76 | 1.00 | 0.76 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 11992 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 11992 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 10072 | 0.84 | 10.00 | 8.40 |
| 15 to 20-years | 1687 | 0.14 | 5.00 | 0.70 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 234 | 0.02 | 1.00 | 0.02 |
| | | | Background Score | 26.13 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3777 | 0.31 | 2.00 | 0.63 |
| Length Outside Damage Area prior to Disaster (ft) | 8216 | 0.69 | 1.00 | 0.69 |
| | | | Damage Score | 1.32 |

| Proximity Analysis | | For the cont | Webber | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 168 | 0.01 | 10.00 | 0.14 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.14 |



| Condition Analysis | | Weighting Factor | | | |
|--|----------|---------------------|-------|--|--|
| Description | Quantity | 1 40101 | Score | | |
| W1 - Damaged Valve | 15 | 0.15 | 2.25 | | |
| W2 - Damaged Hydrant | 9 | 0.15 | 1.35 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 12 | 0.15 | 1.80 | | |
| W6 - Maintenance Event (2004-2014) | 58 | 0.15 | 8.70 | | |
| | | Condition Score | 14.10 | | |

Report Date: 3/10/2015 4:57:55 PM Page 7 of 62

Baer's Westmoore

Assessment Sub-Area BW2

Infrastructure Category Wate

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2022.05.2 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Неа | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Webster. | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery | /Revitalization Score | 15.00 |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | Weighting | | | |
|--|-----------|-------------------|-------|--|
| Project Description | Score | Factor | Score | |
| SUB-AREA BW2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 | |
| | | Opportunity Score | 5.00 | |

Infrastructure Photographs

LMI Score 0.00









Eastern Avenue

Assessment Sub-Area EA1

Infrastructure Category

Water Distribution

Exhibit Group E.5

| Assessment Data | |
|-----------------|-----------------------|
| Description | Value |
| Assessment Rv | .I Cotton / A Hartman |

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 4011 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 3500 | 0.87 | 10.00 | 8.73 |
| Diameter 8-in to 12-in (ft) | 184 | 0.05 | 5.00 | 0.23 |
| Diameter 4-in to 6-in (ft) | 328 | 0.08 | 1.00 | 0.08 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 4011 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 3432 | 0.86 | 10.00 | 8.56 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 579 | 0.14 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 2128 | 0.53 | 10.00 | 5.31 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 1884 | 0.47 | 1.00 | 0.47 |
| | | | Background Score | 28.37 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 265 | 0.07 | 10.00 | 0.66 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 437 | 0.11 | 5.00 | 0.54 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 1311 | 0.33 | 2.00 | 0.65 |
| Length Outside Damage Area prior to Disaster (ft) | 1999 | 0.50 | 1.00 | 0.50 |
| | | | Damage Score | 2.36 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 4011 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |

Key Map SW4TH ST NORTH SW 11TH ST Personal Landon a dictional Constitution

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | ractor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | C | ondition Score | 0.00 |

Report Date: 3/10/2015 4:57:57 PM Page 9 of 62

Eastern Avenue

EA1 **Assessment Sub-Area**

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.05.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|----------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ2

Infrastructure Category Water Distribution

> E.5 **Exhibit Group**

Assessment Data Description

Value

Assessment By J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data | | | W + 1 c | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Total Water Line Length (ft) | 19170 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 2680 | 0.14 | 5.00 | 0.70 |
| Diameter 4-in to 6-in (ft) | 16490 | 0.86 | 1.00 | 0.86 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 19170 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 17029 | 0.89 | 10.00 | 8.88 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 2141 | 0.11 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 19170 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 25.44 |

| Damage Score | | | | |
|---|-------|--------------|--------------|-------|
| | | Fraction of | Weighting | |
| Description | Value | Total Length | Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 1103 | 0.06 | 10.00 | 0.58 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1576 | 0.08 | 5.00 | 0.41 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 9713 | 0.51 | 2.00 | 1.01 |
| Length Outside Damage Area prior to Disaster (ft) | 6778 | 0.35 | 1.00 | 0.35 |
| | | | Damage Score | 2.35 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 19130 | 1.00 | 10.00 | 9.98 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 9.98 |

Key Map EJ2 SE 12TH ST SE 13TH ST 6-N

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | i actor | Score |
| W1 - Damaged Valve | 7 | 0.15 | 1.05 |
| W2 - Damaged Hydrant | 2 | 0.15 | 0.30 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 28 | 0.15 | 4.20 |
| W6 - Maintenance Event (2004-2014) | 51 | 0.15 | 7.65 |
| | C | Condition Score | 13.20 |

Report Date: 3/10/2015 4:57:58 PM Page 11 of 62

Exhibit Group

Eastmoor / JD Estates

EJ2 **Assessment Sub-Area**

Infrastructure Category

Water Distribution

E.5

| | Ir |
|-------|---------|
| Score | |
| 0.00 | 400 |
| 0.00 | |

| LMI Score | 0.00 |
|-------------|------|
| LIVII SCOIE | 0.00 |

Weighting Factor

10.00

5.00

| Health and Safety | | | Web life. | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

Value

40027.2021.05.3

Score

0.00

0.00

| Long Term Recovery / Economic Revitalization | | | Waighting | | | |
|--|-------|----------|---------------------------|-------|--|--|
| Description | Value | Score | Weighting Score Factor | | | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | | |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | | |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | | |
| | | Recovery | Revitalization Score | 20.00 | | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SUB-AREA EJ2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5 00 |

nfrastructure Photographs









Infrastructure Rating Index (IRI)

LMI Benefit

Q28: Census Block Group

Q29: Improvements would benefit LMI Census Block Group?

Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ4

Infrastructure Category Water Distribution

Exhibit Group E.5


| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 617 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 617 | 1.00 | 5.00 | 5.00 |
| Diameter 4-in to 6-in (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 617 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 61 | 0.10 | 10.00 | 0.99 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 556 | 0.90 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 10.99 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 401 | 0.65 | 5.00 | 3.25 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 215 | 0.35 | 2.00 | 0.70 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 3.95 |

| Proximity Analysis | | For the cont | Watabasa | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 617 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | ractor | Score |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | (| Condition Score | 0.15 |

Report Date: 3/10/2015 4:57:59 PM Page 13 of 62

Eastmoor / JD Estates

EJ4 **Assessment Sub-Area**

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.05.3 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | | |
|--|-------|----------|-----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | /Revitalization Score | 0.00 | |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ5

Infrastructure Category Water Distribution

Exhibit Group E.5


| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 23666 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 3124 | 0.13 | 10.00 | 1.32 |
| Diameter 8-in to 12-in (ft) | 3646 | 0.15 | 5.00 | 0.77 |
| Diameter 4-in to 6-in (ft) | 16896 | 0.71 | 1.00 | 0.71 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 23666 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 17464 | 0.74 | 10.00 | 7.38 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 6202 | 0.26 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 23666 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 25.18 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 2414 | 0.10 | 10.00 | 1.02 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 2983 | 0.13 | 5.00 | 0.63 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 7543 | 0.32 | 2.00 | 0.64 |
| Length Outside Damage Area prior to Disaster (ft) | 10726 | 0.45 | 1.00 | 0.45 |
| | | | Damage Score | 2.74 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 11114 | 0.47 | 10.00 | 4.70 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 4.70 |



| Condition Analysis | | Weighting Factor | | |
|--|----------|------------------------|-------|--|
| Description | Quantity | | Score | |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 | |
| W2 - Damaged Hydrant | 5 | 0.15 | 0.75 | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | |
| W4 - Future service connection anticipated | 55 | 0.15 | 8.25 | |
| W6 - Maintenance Event (2004-2014) | 60 | 0.15 | 9.00 | |
| | | Condition Score | 18.15 | |

Report Date: 3/10/2015 4:58:00 PM Page 15 of 62

LMI Benefit

Q28: Census Block Group

Q29: Improvements would benefit LMI Census Block Group?

Assessment Area E

Eastmoor / JD Estates

Assessment Sub-Area

Infrastructure Category V

Water Distribution

EJ5

Exhibit Group E.5

| | lr |
|-------|----|
| Score | |
| 0.00 | |
| 0.00 | |

| LMI Score | 0.00 |
|-------------|------|
| LIVII OCUIE | 0.00 |

10.00

5.00

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

Value

40027.2021.05.3

Score

0.00

0.00

| Long Term Recovery / Economic Revitalization | | | Weighting | | |
|--|-------|----------|-----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| | | Recovery | /Revitalization Score | 15.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|------------------|--------|
| Project Description | Score | Factor | Score |
| SUB-AREA EJ5: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Scor | e 5.00 |

nfrastructure Photographs







Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ6

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Water Line Length (ft) | 252 | • | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 252 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 252 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 144 | 0.57 | 10.00 | 5.71 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 108 | 0.43 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 11.71 |

| Damage Score | | Europe of | W. S. Lee | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 252 | 1.00 | 5.00 | 5.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 5.00 |

| Proximity Analysis | | English | Webber | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | Weighting Factor | | |
|--|---------------------|-----------------|-------|
| Description | Quantity | 1 40101 | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | (| Condition Score | 0.00 |

Report Date: 3/10/2015 4:58:01 PM Page 17 of 62

Eastmoor / JD Estates

Assessment Sub-Area EJ6

Infrastructure Category W

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.05.2 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | |
| | | Hea | lth and Safety Score | 0.00 | |


| Long Term Recovery / Economic Revitalization | | | Web life o | | |
|--|-------|----------|-----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | /Revitalization Score | 10.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|------------------|---------|
| Project Description | Score | Factor | Score |
| SUB-AREA EJ6: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Scor | re 5.00 |


Infrastructure Photographs

LMI Score 0.00









Assessment Area H

Heatherwood

Assessment Sub-Area HW1

Infrastructure Category

Water Distribution

Exhibit Group E.5


| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 7669 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 587 | 0.08 | 5.00 | 0.38 |
| Diameter 4-in to 6-in (ft) | 7082 | 0.92 | 1.00 | 0.92 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 7669 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 671 | 0.09 | 10.00 | 0.87 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 6998 | 0.91 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 3980 | 0.52 | 5.00 | 2.59 |
| 10 to 15-years | 3689 | 0.48 | 4.00 | 1.92 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 11.70 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 661 | 0.09 | 10.00 | 0.86 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1182 | 0.15 | 5.00 | 0.77 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 4954 | 0.65 | 2.00 | 1.29 |
| Length Outside Damage Area prior to Disaster (ft) | 872 | 0.11 | 1.00 | 0.11 |
| | | | Damage Score | 3.04 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | ractor | Score |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 |
| W2 - Damaged Hydrant | 2 | 0.15 | 0.30 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 9 | 0.15 | 1.35 |
| W6 - Maintenance Event (2004-2014) | 14 | 0.15 | 2.10 |
| | | Condition Score | 3.90 |

Report Date: 3/10/2015 4:58:02 PM Page 19 of 62

Heatherwood

HW1

Assessment Sub-Area
Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.07.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | Ilth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Wainhting | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SUB-AREA HW1: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs

LMI Score 0.00









Assessment Area King's Manor

Assessment Sub-Area KM2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 7333 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 2496 | 0.34 | 5.00 | 1.70 |
| Diameter 4-in to 6-in (ft) | 4838 | 0.66 | 1.00 | 0.66 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 7333 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 1654 | 0.23 | 10.00 | 2.26 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 5679 | 0.77 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 7333 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 19.62 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 43 | 0.01 | 5.00 | 0.03 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 5699 | 0.78 | 2.00 | 1.55 |
| Length Outside Damage Area prior to Disaster (ft) | 1591 | 0.22 | 1.00 | 0.22 |
| | | | Damage Score | 1.80 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | Weighting Factor | | | | |
|--|---------------------|-----------------|-------|--|--|
| Description | Quantity | 7 40101 | Score | | |
| W1 - Damaged Valve | 7 | 0.15 | 1.05 | | |
| W2 - Damaged Hydrant | 1 | 0.15 | 0.15 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | | |
| W6 - Maintenance Event (2004-2014) | 13 | 0.15 | 1.95 | | |
| | | Condition Score | 3 15 | | |

Report Date: 3/10/2015 4:58:03 PM Page 21 of 62

Assessment Area King's Manor

Assessment Sub-Area KM2

Infrastructure Category Water Distribution

Exhibit Group E.5

| LMI Benefit | | | | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |
| | | | LMI Score | 15.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Watelation | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery | /Revitalization Score | 20.00 |

| ustainability Weighting | | | | | | |
|--|-------|-------|----------------------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | | |
| | | | Sustainability Score | 0.00 | | |

| Opportunity Score | | Weighting | | | |
|--|-------|-------------------|-------|--|--|
| Project Description | Score | Factor | Score | | |
| SUB-AREA KM2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 | | |
| | | Opportunity Score | 5.00 | | |

Infrastructure Photographs







Assessment Area King's Manor

Assessment Sub-Area KM3

Infrastructure Category Water Distribution

Exhibit Group E.5

| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Waighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Total Water Line Length (ft) | 9022 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 9022 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 9022 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 8948 | 0.99 | 10.00 | 9.92 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 74 | 0.01 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 9022 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 25.92 |

| Damage Score | | Fraction of | Weighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 1888 | 0.21 | 10.00 | 2.09 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1701 | 0.19 | 5.00 | 0.94 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 5433 | 0.60 | 2.00 | 1.20 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 4.24 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 6983 | 0.77 | 10.00 | 7.74 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 6983 | 0.77 | 5.00 | 3.87 |
| | | | Proximity Score | 11.61 |



| Condition Analysis | Weighting Factor | | |
|--|---------------------|-----------------|-------|
| Description | Quantity | 1 40.01 | Score |
| W1 - Damaged Valve | 4 | 0.15 | 0.60 |
| W2 - Damaged Hydrant | 3 | 0.15 | 0.45 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 53 | 0.15 | 7.95 |
| W6 - Maintenance Event (2004-2014) | 37 | 0.15 | 5.55 |
| | | Condition Score | 14.55 |

Report Date: 3/10/2015 4:58:04 PM Page 23 of 62

Exhibit Group

King's Manor

KM3

E.5

Assessment Sub-Area

Infrastructure Category

Water Distribution

| LMI Benefit Weighting | | | | | | |
|---|-----------------|-------|--------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q28: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 | | |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 | | |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Ues | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery | /Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SUB-AREA KM3: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs

LMI Score 15.00









Assessment Area Madison Place / Hunter's Gl

Assessment Sub-Area MH1

Infrastructure Category Water Distribution

Exhibit Group E.5


| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Water Line Length (ft) | 998 | • | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 747 | 0.75 | 5.00 | 3.74 |
| Diameter 4-in to 6-in (ft) | 251 | 0.25 | 1.00 | 0.25 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 998 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 998 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 998 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 28.99 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 998 | 1.00 | 1.00 | 1.00 |
| | | | Damage Score | 1.00 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 998 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | • | Condition Score | 0.00 |

Report Date: 3/10/2015 4:58:05 PM Page 25 of 62

LMI Benefit

Q28: Census Block Group

Q29: Improvements would benefit LMI Census Block Group?

Assessment Area

Madison Place / Hunter's Gl

Assessment Sub-Area MH1

Infrastructure Category V

Water Distribution

Exhibit Group E.5

| | | _ |
|---------------------|-------|---|
| Weighting Factor | Score | |
| 10.00 | 0.00 | |
| 5.00 | 0.00 | |

LMI Score 0.00

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

Value

40027.2021.04.1

Score

0.00

0.00

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | | | |
|-----------------------|-------|---------------------|-------|--|
| Project Description | Score | Weighting Factor | Score | |
| No Projects Available | 0.00 | 0.00 | 0.00 | |

Infrastructure Photographs









Assessment Area Madison Place / Hunter's Gl

Assessment Sub-Area MH2

Infrastructure Category Water Distribution

Exhibit Group E.5

| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| otal Water Line Length (ft) | 13154 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 6157 | 0.47 | 5.00 | 2.34 |
| Diameter 4-in to 6-in (ft) | 6997 | 0.53 | 1.00 | 0.53 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 13154 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 12676 | 0.96 | 10.00 | 9.64 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 477 | 0.04 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 6490 | 0.49 | 10.00 | 4.93 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 5700 | 0.43 | 4.00 | 1.73 |
| less than 10-years | 964 | 0.07 | 2.00 | 0.15 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 24.32 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 992 | 0.08 | 10.00 | 0.75 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1939 | 0.15 | 5.00 | 0.74 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 6008 | 0.46 | 2.00 | 0.91 |
| Length Outside Damage Area prior to Disaster (ft) | 4214 | 0.32 | 1.00 | 0.32 |
| | | | Damage Score | 2.73 |

| Proximity Analysis | | Frantian of | Waishting | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 11539 | 0.88 | 10.00 | 8.77 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 8.77 |



| Condition Analysis | | Weighting Factor | | | |
|--|----------|---------------------|-------|--|--|
| Description | Quantity | ractor | Score | | |
| W1 - Damaged Valve | 2 | 0.15 | 0.30 | | |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 13 | 0.15 | 1.95 | | |
| W6 - Maintenance Event (2004-2014) | 31 | 0.15 | 4.65 | | |
| | C | Condition Score | 6.90 | | |

Report Date: 3/10/2015 4:58:06 PM Page 27 of 62

Madison Place / Hunter's Gl

Assessment Sub-Area MH2

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety Weighting | | | | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|----------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|--|-------|------------------|--------|
| Project Description | Score | Factor | Score |
| SUB-AREA MH2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Scor | e 5.00 |

Infrastructure Photographs

LMI Score 0.00









Assessment Area North 4th Street

Assessment Sub-Area N4A

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Water Line Length (ft) | 5461 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 5291 | 0.97 | 10.00 | 9.69 |
| Diameter 8-in to 12-in (ft) | 90 | 0.02 | 5.00 | 0.08 |
| Diameter 4-in to 6-in (ft) | 80 | 0.01 | 1.00 | 0.01 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 5461 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 5161 | 0.95 | 10.00 | 9.45 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 300 | 0.05 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 2787 | 0.51 | 10.00 | 5.10 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 2675 | 0.49 | 1.00 | 0.49 |
| | | | Background Score | 29.83 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 237 | 0.04 | 5.00 | 0.22 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 533 | 0.10 | 2.00 | 0.20 |
| Length Outside Damage Area prior to Disaster (ft) | 4692 | 0.86 | 1.00 | 0.86 |
| | | | Damage Score | 1.27 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 1299 | 0.24 | 10.00 | 2.38 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 1257 | 0.23 | 5.00 | 1.15 |
| | | | Proximity Score | 3.53 |



| Condition Analysis | | Weighting Factor | | | |
|--|----------|------------------------|-------|--|--|
| Description | Quantity | | Score | | |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 | | |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | | |
| W6 - Maintenance Event (2004-2014) | 7 | 0.15 | 1.05 | | |
| | | Condition Score | 1.20 | | |

Report Date: 3/10/2015 4:58:07 PM Page 29 of 62

North 4th Street

Assessment Sub-Area N4A

Infrastructure Category Wa

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | Ilth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs

LMI Score 5.00









Assessment Area North 4th Street

Assessment Sub-Area N4B

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Woighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Total Water Line Length (ft) | 3775 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 3071 | 0.81 | 10.00 | 8.14 |
| Diameter 8-in to 12-in (ft) | 160 | 0.04 | 5.00 | 0.21 |
| Diameter 4-in to 6-in (ft) | 545 | 0.14 | 1.00 | 0.14 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 3775 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 3521 | 0.93 | 10.00 | 9.33 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 253 | 0.07 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 675 | 0.18 | 10.00 | 1.79 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 3100 | 0.82 | 1.00 | 0.82 |
| | | | Background Score | 25.43 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 99 | 0.03 | 2.00 | 0.05 |
| Length Outside Damage Area prior to Disaster (ft) | 3676 | 0.97 | 1.00 | 0.97 |
| | | | Damage Score | 1.03 |

| Proximity Analysis | | Function of | Mainhainn | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 2382 | 0.63 | 10.00 | 6.31 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 6.31 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | i actor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 4 | 0.15 | 0.60 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 5 | 0.15 | 0.75 |
| | (| Condition Score | 1.35 |

Report Date: 3/10/2015 4:58:08 PM Page 31 of 62

North 4th Street

Assessment Sub-Area N4B

Infrastructure Category

Water Distribution

oit Group E.5

| | Exhibit | Group |
|--|---------|-------|
| | | |

| LMI Benefit | | | Mainhtina | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |
| | | | LMI Score | 5.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Wainkiinn | |
|--|-------|----------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area North 4th Street

Assessment Sub-Area N4C

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| otal Water Line Length (ft) | 6101 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 5305 | 0.87 | 10.00 | 8.70 |
| Diameter 8-in to 12-in (ft) | 90 | 0.01 | 5.00 | 0.07 |
| Diameter 4-in to 6-in (ft) | 706 | 0.12 | 1.00 | 0.12 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 6101 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 4332 | 0.71 | 10.00 | 7.10 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 1768 | 0.29 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 1441 | 0.24 | 10.00 | 2.36 |
| 15 to 20-years | 10 | 0.00 | 5.00 | 0.01 |
| 10 to 15-years | 17 | 0.00 | 4.00 | 0.01 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 4632 | 0.76 | 1.00 | 0.76 |
| | | | Background Score | 24.13 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 838 | 0.14 | 5.00 | 0.69 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3619 | 0.59 | 2.00 | 1.19 |
| Length Outside Damage Area prior to Disaster (ft) | 1644 | 0.27 | 1.00 | 0.27 |
| | | | Damage Score | 2.14 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 4608 | 0.76 | 10.00 | 7.55 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 7.55 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 2 | 0.15 | 0.30 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 7 | 0.15 | 1.05 |
| | Co | ondition Score | 1.35 |

Report Date: 3/10/2015 4:58:09 PM Page 33 of 62

North 4th Street

N4C **Assessment Sub-Area**

Infrastructure Category

Water Distribution

| Exhibit | Group | E.5 |
|---------|-------|-----|
|---------|-------|-----|

| LMI Benefit | | | | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2021.05.3 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area North 4th Street

Assessment Sub-Area N4D

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 3524 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 3313 | 0.94 | 10.00 | 9.40 |
| Diameter 8-in to 12-in (ft) | 201 | 0.06 | 5.00 | 0.29 |
| Diameter 4-in to 6-in (ft) | 10 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 3524 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 1031 | 0.29 | 10.00 | 2.93 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 2493 | 0.71 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 43 | 0.01 | 4.00 | 0.05 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 3481 | 0.99 | 1.00 | 0.99 |
| | | | Background Score | 18.65 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 2100 | 0.60 | 5.00 | 2.98 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 1424 | 0.40 | 2.00 | 0.81 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 3 79 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | 1 actor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 5 | 0.15 | 0.75 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 2 | 0.15 | 0.30 |
| | (| Condition Score | 1.05 |

Report Date: 3/10/2015 4:58:10 PM Page 35 of 62

North 4th Street

Assessment Sub-Area N4D

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.07.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | Ith and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Waterian | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 0.00 |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |


| Opportunity Score | | Weighting | | |
|-----------------------|-------|-----------|-------|--|
| Project Description | Score | Factor | Score | |
| No Projects Available | 0.00 | 0.00 | 0.00 | |

Infrastructure Photographs

LMI Score 0.00









Assessment Area Plaza Towers

Assessment Sub-Area P

Infrastructure Category Water Distribution


Exhibit Group E.5

| Assessment Data | |
|--------------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Woighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Total Water Line Length (ft) | 2614 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 2596 | 0.99 | 10.00 | 9.93 |
| Diameter 8-in to 12-in (ft) | 9 | 0.00 | 5.00 | 0.02 |
| Diameter 4-in to 6-in (ft) | 8 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 2614 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 2415 | 0.92 | 10.00 | 9.24 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 199 | 0.08 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 41 | 0.02 | 5.00 | 0.08 |
| 10 to 15-years | 635 | 0.24 | 4.00 | 0.97 |
| less than 10-years | 628 | 0.24 | 2.00 | 0.48 |
| Unknown | 1309 | 0.50 | 1.00 | 0.50 |
| | | | Background Score | 26.22 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 12 | 0.00 | 10.00 | 0.05 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 219 | 0.08 | 5.00 | 0.42 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 893 | 0.34 | 2.00 | 0.68 |
| Length Outside Damage Area prior to Disaster (ft) | 1490 | 0.57 | 1.00 | 0.57 |
| | | | Damage Score | 1.72 |

| Proximity Analysis | | | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | | |
| Length within 0.25-mi of Critical Water User (ft) | 1633 | 0.62 | 10.00 | 6.25 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 6.25 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | ractor | Score |
| W1 - Damaged Valve | 3 | 0.15 | 0.45 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 1 | 0.15 | 0.15 |
| W4 - Future service connection anticipated | 5 | 0.15 | 0.75 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | | Condition Score | 1.35 |

Report Date: 3/10/2015 4:58:11 PM Page 37 of 62

Assessment Area

Plaza Towers

Assessment Sub-Area

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | | |
|--|-------|-------|-----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | |
| | | Hea | alth and Safety Score | 0.00 | |

| Long Term Recovery / Economic Revitalization | | | Wainhtina | |
|--|-------|----------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | 0.00 | |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs

LMI Score 0.00









Date of Assessment

Assessment Area Plaza Towers

Assessment Sub-Area PT2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value

Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| otal Water Line Length (ft) | 10131 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 1272 | 0.13 | 10.00 | 1.26 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 8859 | 0.87 | 1.00 | 0.87 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 10131 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 10131 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 10131 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 27.13 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 5625 | 0.56 | 10.00 | 5.55 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1931 | 0.19 | 5.00 | 0.95 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 2575 | 0.25 | 2.00 | 0.51 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 7.01 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 9739 | 0.96 | 10.00 | 9.61 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 9.61 |

Key Map SW413TH ST 6-IN PT2 SW 14TH ST

| Condition Analysis | | Weighting Factor | |
|--|----------|------------------------|-------|
| Description | Quantity | | Score |
| W1 - Damaged Valve | 12 | 0.15 | 1.80 |
| W2 - Damaged Hydrant | 4 | 0.15 | 0.60 |
| W3 - Abandoned Meter | 1 | 0.15 | 0.15 |
| W4 - Future service connection anticipated | 87 | 0.15 | 13.05 |
| W6 - Maintenance Event (2004-2014) | 53 | 0.15 | 7.95 |
| | | Condition Score | 23.55 |

Report Date: 3/10/2015 4:58:12 PM Page 39 of 62

Assessment Area

Plaza Towers

Assessment Sub-Area PT2

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-------------------------------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/Revitalization Score | | 20.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainahility Score | 0.00 |

| Opportunity Score Project Description | Score | Weighting Factor | Score |
|--|-------|---------------------|-------|
| SUB-AREA PT2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs









Assessment Area Plaza Towers

Assessment Sub-Area PT3

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Assessment By

Value

J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 8635 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 272 | 0.03 | 10.00 | 0.31 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 8362 | 0.97 | 1.00 | 0.97 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 8635 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 8223 | 0.95 | 10.00 | 9.52 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 412 | 0.05 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 4763 | 0.55 | 10.00 | 5.52 |
| 15 to 20-years | 3473 | 0.40 | 5.00 | 2.01 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 398 | 0.05 | 1.00 | 0.05 |
| | | | Background Score | 23.38 |

| Damage Score | | | 100 - 100 | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 3628 | 0.42 | 10.00 | 4.20 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 2103 | 0.24 | 5.00 | 1.22 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 2047 | 0.24 | 2.00 | 0.47 |
| Length Outside Damage Area prior to Disaster (ft) | 858 | 0.10 | 1.00 | 0.10 |
| | | | Damage Score | 5 99 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 8635 | 1.00 | 10.00 | 10.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 10.00 |

Key Map SW 19TH ST 0

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | i actor | Score |
| W1 - Damaged Valve | 4 | 0.15 | 0.60 |
| W2 - Damaged Hydrant | 3 | 0.15 | 0.45 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 48 | 0.15 | 7.20 |
| W6 - Maintenance Event (2004-2014) | 29 | 0.15 | 4.35 |
| | (| Condition Score | 12.60 |

Report Date: 3/10/2015 4:58:13 PM Page 41 of 62

Assessment Area Pla

Plaza Towers
PT3

Assessment Sub-Area
Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery | /Revitalization Score | 20.00 |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | |
|---|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| SUB-AREA PT3: RECONSTRUCTION OF ALL PUBLIC WATER INFRASTRUCTURE | 1.00 | 5.00 | 5.00 |
| | | Onnortunity Score | 5.00 |

Infrastructure Photographs

LMI Score 0.00









Date of Assessment

City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

3/10/2015

Assessment Area Plaza Towers

Assessment Sub-Area PT4

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data


Description Value

Assessment By J. Cotton / A. Hartman

| Background Data | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Total Water Line Length (ft) | 5363 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 79 | 0.01 | 5.00 | 0.07 |
| Diameter 4-in to 6-in (ft) | 5284 | 0.99 | 1.00 | 0.99 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 5363 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 5207 | 0.97 | 10.00 | 9.71 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 156 | 0.03 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 5363 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 25.77 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 1910 | 0.36 | 10.00 | 3.56 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 805 | 0.15 | 5.00 | 0.75 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 2649 | 0.49 | 2.00 | 0.99 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 5.30 |

| Proximity Analysis | | Fraction of | Waighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 4087 | 0.76 | 10.00 | 7.62 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 7.62 |



| Condition Analysis | | Weighting Factor | |
|--|----------|------------------------|-------|
| Description | Quantity | | Score |
| W1 - Damaged Valve | 4 | 0.15 | 0.60 |
| W2 - Damaged Hydrant | 1 | 0.15 | 0.15 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 88 | 0.15 | 13.20 |
| W6 - Maintenance Event (2004-2014) | 33 | 0.15 | 4.95 |
| | | Condition Score | 18.90 |

Report Date: 3/10/2015 4:58:14 PM Page 43 of 62

Assessment Area

Plaza Towers

Assessment Sub-Area

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery/Revitalization Score | | 20.00 |

| Sustainability | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | Weighting | | | |
|--|-----------|------------------|--------|--|
| Project Description | Score | Factor | Score | |
| SUB-AREA PT4: RECONSTRUCTION OF ALL PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 | |
| | | Opportunity Scor | e 5.00 | |

Infrastructure Photographs

LMI Score 5.00









Date of Assessment

Assessment Area Plaza Towers

Assessment Sub-Area PT5

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value

Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| • | | Total Length | racioi | 30016 |
| Total Water Line Length (ft) | 12665 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 438 | 0.03 | 5.00 | 0.17 |
| Diameter 4-in to 6-in (ft) | 12227 | 0.97 | 1.00 | 0.97 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 12665 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 12665 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 12665 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 26.14 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 208 | 0.02 | 10.00 | 0.16 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1747 | 0.14 | 5.00 | 0.69 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 6894 | 0.54 | 2.00 | 1.09 |
| Length Outside Damage Area prior to Disaster (ft) | 3816 | 0.30 | 1.00 | 0.30 |
| | | | Damage Score | 2.24 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 9099 | 0.72 | 10.00 | 7.18 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 7.18 |

Key Map SW 4TH ST NORTH PT5

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 2 | 0.15 | 0.30 |
| W2 - Damaged Hydrant | 2 | 0.15 | 0.30 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 21 | 0.15 | 3.15 |
| W6 - Maintenance Event (2004-2014) | 106 | 0.15 | 15.90 |
| | | Condition Score | 19.65 |

Report Date: 3/10/2015 4:58:16 PM Page 45 of 62

Assessment Area Plaza
Assessment Sub-Area PT5

Plaza Towers

Infrastructure Category Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Wajahtina | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Wainkiina | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| | | Recovery | /Revitalization Score | 20.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score Project Description | Score | Weighting Factor | Score |
|--|-------|---------------------|-------|
| SUB-AREA PT5: RECONSTRUCTION OF PUBLIC WATER LINE SYSTEM | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs







Infrastructure Rating Index (IRI)

80.22

Report Date: 3/10/2015 4:58:16 PM Page 46 of 62

Assessment Area Santa Fe Avenue

Assessment Sub-Area SF1

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data
Description Value

Date of Assessment 3/10/2015

Assessment By


| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-----------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 2494 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 2355 | 0.94 | 10.00 | 9.44 |
| Diameter 8-in to 12-in (ft) | 139 | 0.06 | 5.00 | 0.28 |
| Diameter 4-in to 6-in (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 2494 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 2494 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 68 | 0.03 | 5.00 | 0.14 |
| 10 to 15-years | 1065 | 0.43 | 4.00 | 1.71 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 1360 | 0.55 | 1.00 | 0.55 |

J. Cotton / A. Hartman

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 81 | 0.03 | 2.00 | 0.06 |
| Length Outside Damage Area prior to Disaster (ft) | 2413 | 0.97 | 1.00 | 0.97 |
| | | | Damage Score | 1.03 |

Background Score 27.11

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 1095 | 0.44 | 10.00 | 4.39 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 4.39 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | ractor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 2 | 0.15 | 0.30 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 4 | 0.15 | 0.60 |
| | (| Condition Score | 0.90 |

Report Date: 3/10/2015 4:58:17 PM Page 47 of 62

Assessment Area Santa Fe Avenue

Assessment Sub-Area SF1

Infrastructure Category Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Walakiaa | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2022.06.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |


| Health and Safety | | | Weighting | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | |
| | | Hea | lth and Safety Score | 0.00 | |

| Long Term Recovery / Economic Revitalization | ecovery / Economic Revitalization | | | | |
|--|-----------------------------------|----------|-----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | /Revitalization Score | 10.00 | |


| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Infrastructure Rating Index (IRI)

Report Date: 3/10/2015 4:58:17 PM Page 48 of 62

Date of Assessment

Assessment Area Santa Fe Avenue

Assessment Sub-Area SF2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

Description Value


Assessment By J. Cotton / A. Hartman

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 4965 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 4806 | 0.97 | 10.00 | 9.68 |
| Diameter 8-in to 12-in (ft) | 16 | 0.00 | 5.00 | 0.02 |
| Diameter 4-in to 6-in (ft) | 144 | 0.03 | 1.00 | 0.03 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 4965 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 4965 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 763 | 0.15 | 10.00 | 1.54 |
| 15 to 20-years | 365 | 0.07 | 5.00 | 0.37 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 304 | 0.06 | 2.00 | 0.12 |
| Unknown | 3533 | 0.71 | 1.00 | 0.71 |
| | | | Background Score | 27.46 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 1120 | 0.23 | 10.00 | 2.26 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 570 | 0.11 | 5.00 | 0.57 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 1386 | 0.28 | 2.00 | 0.56 |
| Length Outside Damage Area prior to Disaster (ft) | 1890 | 0.38 | 1.00 | 0.38 |
| | | | Damage Score | 3.77 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 1420 | 0.29 | 10.00 | 2.86 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 2.86 |



| Condition Analysis | Weighting Factor | | |
|--|---------------------|---------------|-------|
| Description | Quantity | i actor | Score |
| W1 - Damaged Valve | 2 | 0.15 | 0.30 |
| W2 - Damaged Hydrant | 3 | 0.15 | 0.45 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 10 | 0.15 | 1.50 |
| | Col | ndition Score | 2.25 |

Report Date: 3/10/2015 4:58:18 PM Page 49 of 62

Assessment Area Santa Fe Avenue

Assessment Sub-Area SF2

Infrastructure Category Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 10.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainahility Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs

LMI Score 0.00









Assessment Area Southmoor

Assessment Sub-Area SM2

Infrastructure Category Water Distribution

Exhibit Group E.5

Assessment Data

cription Val

Assessment By J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 11074 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 11074 | 1.00 | 1.00 | 1.00 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 11074 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 11074 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 11074 | 1.00 | 10.00 | 10.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 26.00 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 326 | 0.03 | 10.00 | 0.29 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 3478 | 0.31 | 5.00 | 1.57 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3566 | 0.32 | 2.00 | 0.64 |
| Length Outside Damage Area prior to Disaster (ft) | 3704 | 0.33 | 1.00 | 0.33 |
| | | | Damage Score | 2.84 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 2282 | 0.21 | 10.00 | 2.06 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 2282 | 0.21 | 5.00 | 1.03 |
| | | | Proximity Score | 3.09 |

Key Map



| | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 1 | 0.15 | 0.15 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 22 | 0.15 | 3.30 |
| W6 - Maintenance Event (2004-2014) | 68 | 0.15 | 10.20 |
| | | Condition Score | 13.65 |

Report Date: 3/10/2015 4:58:19 PM Page 51 of 62

Assessment Area S

Southmoor

Assessment Sub-Area SM2

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |

| Health and Safety Weighting | | | | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |


| Long Term Recovery / Economic Revitalization | | | Web life o | | |
|--|-------|----------|-----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| | | Recovery | /Revitalization Score | 15.00 | |

| Sustainability Weighting | | | | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score Project Description | Score | Weighting Factor | Score |
|--|-------|---------------------|-------|
| SUB-AREA SM2: REPLACEMENT OF ALL EXISTING PUBLIC WATER LINES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs

LMI Score 0.00









Assessment Area Tower Drive District

Assessment Sub-Area TD3

Infrastructure Category Water Distribution


Exhibit Group E.5

| Assessment Data | |
|--------------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |
| Date of Assessment | 3/10/2015 |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 2023 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 841 | 0.42 | 10.00 | 4.16 |
| Diameter 8-in to 12-in (ft) | 903 | 0.45 | 5.00 | 2.23 |
| Diameter 4-in to 6-in (ft) | 279 | 0.14 | 1.00 | 0.14 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 2023 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 2023 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 1619 | 0.80 | 10.00 | 8.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 0 | 0.00 | 2.00 | 0.00 |
| Unknown | 404 | 0.20 | 1.00 | 0.20 |
| | | | Background Score | 29.73 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 526 | 0.26 | 5.00 | 1.30 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 362 | 0.18 | 2.00 | 0.36 |
| Length Outside Damage Area prior to Disaster (ft) | 1135 | 0.56 | 1.00 | 0.56 |
| | | | Damage Score | 2.22 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 553 | 0.27 | 10.00 | 2.73 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 2.73 |



| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | Co | ndition Score | 0.00 |

Report Date: 3/10/2015 4:58:20 PM Page 53 of 62

Assessment Area To

Exhibit Group

Tower Drive District

Assessment Sub-Area

Infrastructure Category Water

E.5

TD3

Water Distribution

| Infrastructure Ph | notographs |
|-------------------|------------|
|-------------------|------------|



| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|--------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | He | olth and Safety Scor | e 0.00 |


| Long Term Recovery / Economic Revitalization | | | Weighting | | |
|--|-------|----------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | Revitalization Score | 10.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Proiects Available | 0.00 | 0.00 | 0.00 |









Date of Assessment

Assessment Area T

Telephone Road

Assessment Sub-Area

Infrastructure Category Water Distribution

Exhibit Group E.5

| Assessment Data | |
|-----------------|------------------------|
| Description | Value |
| Assessment By | J. Cotton / A. Hartman |

3/10/2015

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Total Water Line Length (ft) | 5840 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 5343 | 0.91 | 10.00 | 9.15 |
| Diameter 8-in to 12-in (ft) | 188 | 0.03 | 5.00 | 0.16 |
| Diameter 4-in to 6-in (ft) | 309 | 0.05 | 1.00 | 0.05 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 5840 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 5201 | 0.89 | 10.00 | 8.91 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 639 | 0.11 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 2657 | 0.45 | 10.00 | 4.55 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 49 | 0.01 | 2.00 | 0.02 |
| Unknown | 3133 | 0.54 | 1.00 | 0.54 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 1224 | 0.21 | 5.00 | 1.05 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 2636 | 0.45 | 2.00 | 0.90 |
| Length Outside Damage Area prior to Disaster (ft) | 887 | 0.15 | 1.00 | 0.15 |
| | | | Damage Score | 2.10 |

Background Score 28.37

| oximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 3054 | 0.52 | 10.00 | 5.23 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 3054 | 0.52 | 5.00 | 2.61 |
| | | | Proximity Score | 7.84 |

Key Map SW 4TH PL SW 4TH ST

| Condition Analysis | | Weighting Factor | |
|--|----------|---------------------|-------|
| Description | Quantity | | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | | Condition Score | 0.00 |

Report Date: 3/10/2015 4:58:22 PM Page 55 of 62

Assessment Area Telephone Road

Assessment Sub-Area TP1

Infrastructure Category

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |
| | | | LMI Score | 15.00 |

| Health and Safety Weighting | | | | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 10.00 |

| Sustainability | | | | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 | |
| | | | Sustainability Score | 0.00 | |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area Tower Drive

Assessment Sub-Area TW1

Infrastructure Category Water Distribution

> **Exhibit Group** E.5

Assessment Data

Assessment By J. Cotton / A. Hartman

Date of Assessment 3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 1961 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Diameter 8-in to 12-in (ft) | 1948 | 0.99 | 5.00 | 4.97 |
| Diameter 4-in to 6-in (ft) | 13 | 0.01 | 1.00 | 0.01 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 1961 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 1961 | 1.00 | 10.00 | 10.00 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 0 | 0.00 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 1079 | 0.55 | 10.00 | 5.50 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 25 | 0.01 | 2.00 | 0.03 |
| Unknown | 856 | 0.44 | 1.00 | 0.44 |
| | | | Background Score | 25.94 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 248 | 0.13 | 10.00 | 1.26 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 655 | 0.33 | 5.00 | 1.67 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 419 | 0.21 | 2.00 | 0.43 |
| Length Outside Damage Area prior to Disaster (ft) | 639 | 0.33 | 1.00 | 0.33 |
| | | | Damage Score | 3.69 |

| Proximity Analysis | | Europe and | Webbbs | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 484 | 0.25 | 10.00 | 2.47 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Provimity Score | 2 /17 |

Key Map



| Condition Analysis | | Weighting Factor | | | |
|--|----------|---------------------|-------|--|--|
| Description | Quantity | racioi | Score | | |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 | | |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 | | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | | |
| W6 - Maintenance Event (2004-2014) | 3 | 0.15 | 0.45 | | |
| | Co | ondition Score | 0.60 | | |

Report Date: 3/10/2015 4:58:23 PM Page 57 of 62

Assessment Area Tower Drive Assessment Sub-Area

TW1

Infrastructure Category Water Distribution

> **Exhibit Group** E.5

| LMI Benefit | | | Wajahtina | |
|---|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q28: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q29: Improvements would benefit LMI Census Block Group? | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Mainhtina | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 10.00 |

| Sustainability Weighting | | | | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | | |
|-----------------------|-------|-----------|-------|--|
| Project Description | Score | Factor | Score | |
| No Projects Available | 0.00 | 0.00 | 0.00 | |

Infrastructure Photographs







Infrastructure Rating Index (IRI)

42.69

Report Date: 3/10/2015 4:58:23 PM Page 58 of 62

Assessment Area Warren Theater

Assessment Sub-Area WT1

Infrastructure Category Water Distribution


Exhibit Group E.5

| Assessment Data | | |
|--------------------|------------------------|--|
| Description | Value | |
| Assessment By | J. Cotton / A. Hartman | |
| Date of Assessment | 3/10/2015 | |

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 6517 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 1392 | 0.21 | 10.00 | 2.14 |
| Diameter 8-in to 12-in (ft) | 3946 | 0.61 | 5.00 | 3.03 |
| Diameter 4-in to 6-in (ft) | 1179 | 0.18 | 1.00 | 0.18 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 6517 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 5675 | 0.87 | 10.00 | 8.71 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 842 | 0.13 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 2461 | 0.38 | 10.00 | 3.78 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 4056 | 0.62 | 2.00 | 1.24 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 24.07 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 2781 | 0.43 | 5.00 | 2.13 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 3736 | 0.57 | 2.00 | 1.15 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 3.28 |

| Proximity Analysis | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 6364 | 0.98 | 10.00 | 9.77 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 6364 | 0.98 | 5.00 | 4.88 |
| | | | Proximity Score | 14.65 |



| | | Weighting Factor | | |
|--|----------|---------------------|-------|--|
| Description | Quantity | 1 actor | Score | |
| W1 - Damaged Valve | 1 | 0.15 | 0.15 | |
| W2 - Damaged Hydrant | 4 | 0.15 | 0.60 | |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 | |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 | |
| W6 - Maintenance Event (2004-2014) | 2 | 0.15 | 0.30 | |
| | (| Condition Score | 1.05 | |

Report Date: 3/10/2015 4:58:24 PM Page 59 of 62

LMI Benefit

Q28: Census Block Group

Q29: Improvements would benefit LMI Census Block Group?

Assessment Area

Warren Theater


Assessment Sub-Area WT1

Infrastructure Category

Water Distribution

Exhibit Group E.5

| Infrastructure Photographs |
|------------------------------|
| illiastiucture Filotograpiis |
| * ' |



| Health and Safety | Weighting | | | | |
|--|-----------|-------|-----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | |
| | | На | alth and Safety Score | 0.00 | |

Value

40027.2016.04.2

Score

1.00

1.00

10.00

5.00

| Long Term Recovery / Economic Revitalization | | | | | |
|--|-------|----------|-----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q33: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery | /Revitalization Score | 10.00 | |

| Sustainability | | | | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Орр | portunity Score | | Weighting | |
|-------|-------------------|-------|-----------|-------|
| Proje | ect Description | Score | Factor | Score |
| No P | rojects Available | 0.00 | 0.00 | 0.00 |









Date of Assessment

Assessment Area Warren Theater

Assessment Sub-Area WT3

Infrastructure Category Water Distribution

Exhibit Group E.5


| Assessment Data | | |
|-----------------|------------------------|--|
| Description | Value | |
| Assessment By | J. Cotton / A. Hartman | |

3/10/2015

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|------------------|-------|
| Description | Value | Total Length | Factor | Score |
| Total Water Line Length (ft) | 411 | | | |
| Line Size | | | | |
| Diameter 12-in or greater (ft) | 330 | 0.80 | 10.00 | 8.03 |
| Diameter 8-in to 12-in (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Diameter 4-in to 6-in (ft) | 81 | 0.20 | 1.00 | 0.20 |
| Material | | | | |
| Length of Cast Iron (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length of PVC (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length of Other (ft) | 411 | 1.00 | 5.00 | 5.00 |
| Corrosion | | | | |
| NRCS "High Steel Corrosion Potential" Map Unit (ft) | 246 | 0.60 | 10.00 | 5.99 |
| NRCS "Moderate Steel Corrosion Potential" Map Unit (ft) | 165 | 0.40 | 0.00 | 0.00 |
| Age | | | | |
| More than 20-years | 0 | 0.00 | 10.00 | 0.00 |
| 15 to 20-years | 0 | 0.00 | 5.00 | 0.00 |
| 10 to 15-years | 0 | 0.00 | 4.00 | 0.00 |
| less than 10-years | 411 | 1.00 | 2.00 | 2.00 |
| Unknown | 0 | 0.00 | 1.00 | 0.00 |
| | | | Background Score | 21.21 |

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 411 | 1.00 | 1.00 | 1.00 |
| | | | Damage Score | 1 00 |

| Proximity Analysis | | Function of | Mainhain n | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Critical Water User (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within 0.25-mi of Emergency Response Facility (ft) | 0 | 0.00 | 5.00 | 0.00 |
| | | | Proximity Score | 0.00 |



| Condition Analysis | Weighting Factor | | |
|--|---------------------|-----------------|-------|
| Description | Quantity | Factor | Score |
| W1 - Damaged Valve | 0 | 0.15 | 0.00 |
| W2 - Damaged Hydrant | 0 | 0.15 | 0.00 |
| W3 - Abandoned Meter | 0 | 0.15 | 0.00 |
| W4 - Future service connection anticipated | 0 | 0.15 | 0.00 |
| W6 - Maintenance Event (2004-2014) | 0 | 0.15 | 0.00 |
| | (| Condition Score | 0.00 |

Report Date: 3/10/2015 4:58:25 PM Page 61 of 62

Assessment Area

Warren Theater

Assessment Sub-Area WT3

Infrastructure Category Water

Water Distribution

Exhibit Group E.5

| LMI Benefit | | | Weighting | |
|---|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q28: Census Block Group | 40027.2016.04.2 | 1.00 | 10.00 | 10.00 |
| Q29: Improvements would benefit LMI Census Block Group? | Yes | 1.00 | 5.00 | 5.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q30: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalization | | | Weighting | |
|--|-------|----------|-----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q31: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 |
| Q32: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 |
| Q33: Historic capacity / load / design issue with infrastructure | No | 0.00 | 10.00 | 0.00 |
| Q34: Projected capacity issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| Q35: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery | /Revitalization Score | 0.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q36: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Орро | rtunity Score | | Weighting | |
|--------|-----------------|-------|-----------|-------|
| Projec | Description | Score | Factor | Score |
| No Pro | iects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs

LMI Score 15.00









City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Bryant Avenue

Assessment Sub-Area BA1

Infrastructure Category Bikeways/Trails

Condition Score

2.50

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data Description | Value | Fraction of Total Length | Weighting Factor | Score |
|---|-------|-----------------------------|---------------------|-------|
| Bikeways | | . . | | |
| 2012 Master Plan (ft) | 57 | | | |
| Proposed: Portion along arterial roadways (ft) | 0 | | | |
| Proposed: Portion along collector roadways (ft) | 0 | | | |
| Existing: Portion along local roadways (ft) | 57 | | | |
| Trails | | | | |
| Existing (ft) | 2124 | | | |
| Proposed (ft) | 1422 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 2181 | 0.61 | 1.00 | 0.61 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 1422 | 0.39 | 5.00 | 1.97 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 1422 | 1.00 | 5.00 | 5.00 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | | |

| Proximity Analysis | | | | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 1034 | 0.29 | 5.00 | 1.43 |
| Length within 0.25-mi of Junior High School (ft) | 0 | 0.00 | 4.00 | 0.00 |
| Length within 0.25-mi of Park (ft) | 3557 | 0.99 | 3.00 | 2.96 |
| Length within 0.25-mi of Community Center (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length within 0.25-mi of Library (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Proximity Score | 4.40 |

Background Score 7.58

| Damage Score | | | w | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 196 | 0.09 | 10.00 | 0.90 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 204 | 0.09 | 5.00 | 0.47 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 1039 | 0.48 | 2.00 | 0.95 |
| Length Outside Damage Area prior to Disaster (ft) | 743 | 0.34 | 1.00 | 0.34 |
| | | | Damage Score | 2.66 |

Key Map SE 4TH ST SECULIATION OF THE STATE OF THE COLDISE 5TH ST. 11-10-10 Dea SE STH ST NORTH 070 SE 6TH CIR COCCO O Legend SE 6TH'ST SE 6TH ST Path 2022 Bike Routes 3000000 Adjacent to Arterial SE 7TH ST Adjacent to Collector Adjacent to Local 300000000 Unrecorded Trail Infrastructure 00000000 Path 2022 Trails FERRESER Multi-Use Trail 900 0 OCH STORY Visionary Trail Sidewalks SOPOCE SE 11TH ST O DODPESE 12TH ST OC SE 13TH ST ackoloppeor br DOPPOSE 14TH STOP agacapacap, a SE 15TH STORE DEL FSE 16TH ST 0 0

| Condition Analysis | | | | | | W . I . | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 3 | 0.25 | 0.75 |
| BW4 - Panel Cracking | 2 | 0.25 | 0.50 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 |
| BW6 - Curb Ramps not Present | 1 | 0.25 | 0.25 | BW13 - Evidence of Recent Repair Work | 1 | 0.25 | 0.25 |
| BW7 - Sidewalk Missing/not Continuous | 3 | 0.25 | 0.75 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 |

Report Date: 3/10/2015 4:40:15 PM Page 1 of 80

Assessment Area Bryan
Assessment Sub-Area BA1

Bryant Avenue

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

| LMI Benefit | | | Mainhtina | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q46c: Census Block Group | 40027.2021.07.1 | 0.00 | 10.00 | 0.00 |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalizatio | | | | | |
|--|-------|-----------|----------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q49: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q50: Current condition may be deterring reinvestment | No | 0.00 | 5.00 | 0.00 | |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery/ | Revitalization Score | 15.00 | |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q54: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









Assessment Area Bryant Avenue

Assessment Sub-Area BA2

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data | | Fraction of | MI. 1. 1. 1 | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Bikeways | | | | |
| 2012 Master Plan (ft) | 28 | | | |
| Proposed: Portion along arterial roadways (ft) | 0 | | | |
| Proposed: Portion along collector roadways (ft) | 28 | | | |
| Existing: Portion along local roadways (ft) | 0 | | | |
| Trails | | | | |
| Existing (ft) | 0 | | | |
| Proposed (ft) | 5222 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 5250 | 1.00 | 5.00 | 5.00 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 4725 | 0.90 | 5.00 | 4.50 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 5250 | 1.00 | 1.00 | 1.00 |

| Proximity Analysis | | | | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within 0.25-mi of Junior High School (ft) | 0 | 0.00 | 4.00 | 0.00 |
| Length within 0.25-mi of Park (ft) | 2210 | 0.42 | 3.00 | 1.26 |
| Length within 0.25-mi of Community Center (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length within 0.25-mi of Library (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Proximity Score | 1.26 |

Background Score 10.50

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

Key Map 0 NORTH JACOBOLOGIC Legend Path 2022 Bike Routes Adjacent to Arterial Adjacent to Collector NE 1ST ST 8 Adjacent to Local Unrecorded Trail Infrastructure Path 2022 Trails E MAIN ST 四公 5 Visionary Trail FFT Sidewalks SE 2ND ST SE 3RD ST SE 4TH ST

| Condition Analysis | | Watabeta | | | | Web Liber | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 0 | 0.25 | 0.00 |
| BW4 - Panel Cracking | 0 | 0.25 | 0.00 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 |
| BW6 - Curb Ramps not Present | 0 | 0.25 | 0.00 | BW13 - Evidence of Recent Repair Work | 0 | 0.25 | 0.00 |
| BW7 - Sidewalk Missing/not Continuous | 0 | 0.25 | 0.00 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 |

Condition Score 0.00

Report Date: 3/10/2015 4:40:16 PM Page 3 of 80

Assessment Area

Bryant Avenue

BA2 **Assessment Sub-Area**

Infrastructure Category

Bikeways/Trails

| Exilibit Gloup L.O | Exhibit | Group | E.6 |
|--------------------|---------|-------|-----|
|--------------------|---------|-------|-----|

| LMI Benefit | | | | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q46c: Census Block Group | 40027.2021.06.1 | 0.00 | 10.00 | 0.00 |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | I MI Score | 0.00 |


| Health and Safety Weighting | | | | | | |
|--|-------|-------|-----------------------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | | |
| | | Но | alth and Safety Score | 0.00 | | |

| Long Term Recovery / Economic Revitalizatio | | | | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q49: Opportunity to improve community asethetic | Yes | 1.00 | 5.00 | 5.00 |
| Q50: Current condition may be deterring reinvestment | Yes | 1.00 | 5.00 | 5.00 |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 25.00 |

| Sustainability Weighting | | | | | |
|--|-------|-------|----------------------|-------|--|
| Description | Value | Score | Factor | Score | |
| Q54: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 | |
| | | | Sustainability Score | 5.00 | |

| Opportunity Score | | Weighting | |
|---|-------|-------------------|-------|
| Project Description | Score | Factor | Score |
| BA2: 10-FT MULTI-USE TRAIL, VETERAN'S PARK TO MAIN STREET | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs









City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Broadway Avenue

Assessment Sub-Area BR1

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Bikeways | | | | |
| 2012 Master Plan (ft) | 5139 | | | |
| Proposed: Portion along arterial roadways (ft) | 5139 | | | |
| Proposed: Portion along collector roadways (ft) | 0 | | | |
| Existing: Portion along local roadways (ft) | 0 | | | |
| Trails | | | | |
| Existing (ft) | 0 | | | |
| Proposed (ft) | 3904 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 9043 | 1.00 | 5.00 | 5.00 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 9043 | 1.00 | 5.00 | 5.00 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 0 | 0.00 | 1.00 | 0.00 |

| Proximity Analysis | | | | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within 0.25-mi of Junior High School (ft) | 0 | 0.00 | 4.00 | 0.00 |
| Length within 0.25-mi of Park (ft) | 0 | 0.00 | 3.00 | 0.00 |
| Length within 0.25-mi of Community Center (ft) | 5142 | 0.57 | 1.00 | 0.57 |
| Length within 0.25-mi of Library (ft) | 729 | 0.08 | 1.00 | 0.08 |
| | | | Proximity Score | 0.65 |

Background Score 10.00

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

| кеу мар | | | | |
|------------------------------------|--|--|--|------------|
| TH PL SW4TH ST | SW4THST | SW4TH ST SE 3RD ST | SE 3RD ST | 1 |
| NORTH Legend Path 2022 Bike Routes | S TELEPHONE RD S TELEPHONE RD | SW.13TH.ST. SW.10TH.ST. SW.10TH.ST. SW.10TH.ST. SW.12TH.ST. SW.13TH.ST. SW.13TH.ST. SW.13TH.ST. SW.14TH.ST. SW.14T | SE 3RD ST OWN SE 4TH ST OWN SE 4TH ST OWN SE 5TH ST OWN ADJSON OF STONE SE 12TH ST OWN ADJSON OWN SE 12TH ST OWN ADJSON OWN SE 12TH ST OWN ADJSON OWN ADJS | SE 12TH ST |

| Condition Analysis | | | | | | | | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|--|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score | |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 | |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 | |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 0 | 0.25 | 0.00 | |
| BW4 - Panel Cracking | 0 | 0.25 | 0.00 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 | |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 | |
| BW6 - Curb Ramps not Present | 0 | 0.25 | 0.00 | BW13 - Evidence of Recent Repair Work | 0 | 0.25 | 0.00 | |
| BW7 - Sidewalk Missing/not Continuous | 0 | 0.25 | 0.00 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 | |
| | | | | | C | ondition Score | 0.00 | |

Report Date: 3/10/2015 4:40:17 PM Page 5 of 80

Assessment Area Br

Exhibit Group

Broadway Avenue

Assessment Sub-Area

Infrastructure Category B

Bikeways/Trails

BR1

E.6

| LMI Benefit | | | Weighting | |
|--|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q46c: Census Block Group | 40027.2021.04.1 | 0.00 | 10.00 | 0.00 |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |

| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalizatio | | | | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q49: Opportunity to improve community asethetic | Yes | 1.00 | 5.00 | 5.00 |
| Q50: Current condition may be deterring reinvestment | Yes | 1.00 | 5.00 | 5.00 |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 25.00 |


| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q54: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

| Opportunity Score Weighting | | | | | |
|--|-------|-------------------|-------|--|--|
| Project Description | Score | Factor | Score | | |
| BR1: NEW MULTI-USE TRAIL, EAST SIDE OF S. BROADWAY, ADJACENT TO NEW PARK | 1.00 | 5.00 | 5.00 | | |
| | | Onnortunity Score | 5.00 | | |

Infrastructure Photographs









Assessment Area Baer's Westmoore

Assessment Sub-Area BW2

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data | | Fraction of | Wainbiinn | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Bikeways | | | | |
| 2012 Master Plan (ft) | 1441 | | | |
| Proposed: Portion along arterial roadways (ft) | 0 | | | |
| Proposed: Portion along collector roadways (ft) | 1441 | | | |
| Existing: Portion along local roadways (ft) | 0 | | | |
| Trails | | | | |
| Existing (ft) | 0 | | | |
| Proposed (ft) | 0 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 1441 | 1.00 | 5.00 | 5.00 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 1441 | 1.00 | 5.00 | 5.00 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 0 | 0.00 | 1.00 | 0.00 |

| Proximity Analysis | | | | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 969 | 0.67 | 5.00 | 3.36 |
| Length within 0.25-mi of Junior High School (ft) | 170 | 0.12 | 4.00 | 0.47 |
| Length within 0.25-mi of Park (ft) | 1441 | 1.00 | 3.00 | 3.00 |
| Length within 0.25-mi of Community Center (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length within 0.25-mi of Library (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Proximity Score | 6.83 |

Background Score 10.00

| Damage Score | | Forestion of | Walabia | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

Key Map SW 149TH ST NORTH SW 20TH ST Legend Path 2022 Bike Routes Adjacent to Arterial Adjacent to Collector Adjacent to Local BW2 SW-21ST-ST SW 21ST ST

| Condition Analysis | | | | | | | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 0 | 0.25 | 0.00 |
| BW4 - Panel Cracking | 2 | 0.25 | 0.50 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 |
| BW6 - Curb Ramps not Present | 0 | 0.25 | 0.00 | BW13 - Evidence of Recent Repair Work | 0 | 0.25 | 0.00 |
| BW7 - Sidewalk Missing/not Continuous | 0 | 0.25 | 0.00 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 |
| | | | | | C | ondition Score | 0.50 |

Report Date: 3/10/2015 4:40:17 PM Page 7 of 80

Assessment Area Baer's Westmoore

Assessment Sub-Area BW2

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

| LMI Benefit | | | Weighting | |
|--|-----------------|-------|-----------|-------|
| Description | Value | Score | Factor | Score |
| Q46c: Census Block Group | 40027.2022.05.2 | 0.00 | 10.00 | 0.00 |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |

| Health and Safety Weighting | | | | | | |
|--|-------|-------|----------------------|-------|--|--|
| Description | Value | Score | Factor | Score | | |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 | | |
| | | Hea | lth and Safety Score | 0.00 | | |

| Long Term Recovery / Economic Revitalizatio | | | | |
|--|-------|-----------|----------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q49: Opportunity to improve community asethetic | Yes | 1.00 | 5.00 | 5.00 |
| Q50: Current condition may be deterring reinvestment | Yes | 1.00 | 5.00 | 5.00 |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/ | Revitalization Score | 25.00 |

| Sustainability | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q54: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 |
| | | | Sustainability Score | 5.00 |

| Opportunity Score | | Wainhtinn | |
|--|-------|---------------------|-------|
| Project Description | Score | Weighting Factor | Score |
| BW2: DEDICATED BIKE LANE, ALL TYPE A CORRIDORS IDENTIFIED IN STREETSCAPE ASSES | 1.00 | 5.00 | 5.00 |
| | | Opportunity Score | 5.00 |

Infrastructure Photographs

LMI Score 0.00











City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Eastern Avenue

Assessment Sub-Area EA1

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|-----------|-------|
| Description | Value | Total Length | Factor | Score |
| Bikeways | | | | |
| 2012 Master Plan (ft) | 76 | | | |
| Proposed: Portion along arterial roadways (ft) | 0 | | | |
| Proposed: Portion along collector roadways (ft) | 76 | | | |
| Existing: Portion along local roadways (ft) | 0 | | | |
| Trails | | | | |
| Existing (ft) | 0 | | | |
| Proposed (ft) | 100 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 176 | 1.00 | 5.00 | 5.00 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 176 | 1.00 | 5.00 | 5.00 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | | |

| Proximity Analysis | | Franklin of | W. C. L.C. | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within 0.25-mi of Junior High School (ft) | 0 | 0.00 | 4.00 | 0.00 |
| Length within 0.25-mi of Park (ft) | 176 | 1.00 | 3.00 | 3.00 |
| Length within 0.25-mi of Community Center (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length within 0.25-mi of Library (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Proximity Score | 3.00 |

Background Score 10.00

| Damage Score | | | | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

Key Map SW 3RD STSE 3RD ST SE/3RD/ST SE 5TH ST SW4TH ST SW 4TH ST SESTH STO NORTH 0 SE 6TH ST SE 6TH ST Legend Path 2022 Bike Routes SE 8TH ST Adjacent to Arterial Adjacent to Collector SE 8TH ST SE 9TH ST Adjacent to Local MADISON A ACEDRY Unrecorded Trail Infrastructure SE 10TH STORE Path 2022 Trails 50504505056 MADISON CT Visionary Trail SE 12TH ST SW 13TH ST SE 13TH ST SE 14TH ST SW 14 TH ST SE:14TH ST 10 SW-15TH ST SE 15TH ST SW(16TH ST SE 16TH ST SECONDER !

| Condition Analysis | | | | | | | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 0 | 0.25 | 0.00 |
| BW4 - Panel Cracking | 0 | 0.25 | 0.00 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 |
| BW6 - Curb Ramps not Present | 0 | 0.25 | 0.00 | BW13 - Evidence of Recent Repair Work | 0 | 0.25 | 0.00 |
| BW7 - Sidewalk Missing/not Continuous | 0 | 0.25 | 0.00 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 |
| | | | | | | Condition Score | 0.00 |

Report Date: 3/10/2015 4:40:18 PM Page 9 of 80

Assessment Area

Exhibit Group

Eastern Avenue

EA1 **Assessment Sub-Area**

Infrastructure Category

Bikeways/Trails

E.6

| LMI Benefit | | | Waighting | |
|--|-----------------|-------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q46c: Census Block Group | 40027.2021.05.1 | 0.00 | 10.00 | 0.00 |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 |
| | | | LMI Score | 0.00 |


| Health and Safety | | | Weighting | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | Hea | lth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalizatio | | | | |
|--|-------|-------------------------------|---------------------|-------|
| Description | Value | Score | Weighting Factor | Score |
| Q49: Opportunity to improve community asethetic | Yes | 1.00 | 5.00 | 5.00 |
| Q50: Current condition may be deterring reinvestment | Yes | 1.00 | 5.00 | 5.00 |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 |
| | | Recovery/Revitalization Score | | 25.00 |

| Sustainability Weighting | | | | | | | |
|--|-------|-------|----------------------|-------|--|--|--|
| Description | Value | Score | Factor | Score | | | |
| Q54: Opportunity for introduction of sustainable design concepts | Yes | 1.00 | 5.00 | 5.00 | | | |
| | | | Sustainability Score | 5.00 | | | |

| Opportunity Score | | Weighting | |
|-----------------------|-------|-----------|-------|
| Project Description | Score | Factor | Score |
| No Projects Available | 0.00 | 0.00 | 0.00 |

Infrastructure Photographs









City of Moore Infrastructure Recovery and Implementation Plan Infrastructure Assessment Form

Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ1

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

Assessment Data

Description Value

Assessment By J.Cotton / N. Clair

Date Range of Assessment

| Background Data | | Fraction of | Weighting | |
|---|-------|--------------|---------------------|-------|
| Description | Value | Total Length | Weighting Factor | Score |
| Bikeways | | | | |
| 2012 Master Plan (ft) | 0 | | | |
| Proposed: Portion along arterial roadways (ft) | 0 | | | |
| Proposed: Portion along collector roadways (ft) | 0 | | | |
| Existing: Portion along local roadways (ft) | 0 | | | |
| Trails | | | | |
| Existing (ft) | 0 | | | |
| Proposed (ft) | 0 | | | |
| Total Inventory | | | | |
| Length of Bikeways/Trails completed (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length of Bikeways/Trails remaining to be constructed (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Available Right-of-Way/Easements | | | | |
| Q46a: Length of bikeways/trails to be constructed where sufficient right-of-way exists (ft) | 0 | 0.50 | 5.00 | 2.50 |
| Q46b: Length of bikeways/trails to be constructed where insufficient right-of-way exists (ft) | 0 | 0.50 | 1.00 | 0.50 |

| Proximity Analysis | | Frankling of | Mariabata a | |
|--|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within 0.25-mi of Elementary School (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within 0.25-mi of Junior High School (ft) | 0 | 0.00 | 4.00 | 0.00 |
| Length within 0.25-mi of Park (ft) | 0 | 0.00 | 3.00 | 0.00 |
| Length within 0.25-mi of Community Center (ft) | 0 | 0.00 | 1.00 | 0.00 |
| Length within 0.25-mi of Library (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Proximity Score | 0.00 |

Background Score 3.00

| Damage Score | | Function of | Wainbiinn | |
|---|-------|-----------------------------|---------------------|-------|
| Description | Value | Fraction of Total Length | Weighting Factor | Score |
| Length within EF4 to EF5 Damage Area prior to disaster (ft) | 0 | 0.00 | 10.00 | 0.00 |
| Length within EF2 to EF4 Damage Area prior to disaster (ft) | 0 | 0.00 | 5.00 | 0.00 |
| Length within EF0 to EF2 Damage Area prior to disaster (ft) | 0 | 0.00 | 2.00 | 0.00 |
| Length Outside Damage Area prior to Disaster (ft) | 0 | 0.00 | 1.00 | 0.00 |
| | | | Damage Score | 0.00 |

Key Map SE 4TH ST NORTH Legend EJ1 Path 2022 Bike Routes Adjacent to Arterial Adjacent to Collector Adjacent to Local Unrecorded Trail Infrastructure Path 2022 Trails

| Condition Analysis | | W | | | | | |
|---------------------------------------|----------|---------------------|-------|--|----------|---------------------|-------|
| Description | Quantity | Weighting Factor | Score | Description | Quantity | Weighting Factor | Score |
| BW1 - Surface Spall | 0 | 0.25 | 0.00 | BW8 - Logitudinal Slope > 5% | 0 | 0.25 | 0.00 |
| BW2 - Joint Deflection | 0 | 0.25 | 0.00 | BW9 - Cross Slope > 2% | 0 | 0.25 | 0.00 |
| BW3 - Panel Settlment | 0 | 0.25 | 0.00 | BW10 - not ADA Compliant at intersection | 0 | 0.25 | 0.00 |
| BW4 - Panel Cracking | 0 | 0.25 | 0.00 | BW11 - Evidence of Ponding | 0 | 0.25 | 0.00 |
| BW5 - Obstructions Present | 0 | 0.25 | 0.00 | BW12 - Anticipated Future Damage | 0 | 0.25 | 0.00 |
| BW6 - Curb Ramps not Present | 0 | 0.25 | 0.00 | BW13 - Evidence of Recent Repair Work | 0 | 0.25 | 0.00 |
| BW7 - Sidewalk Missing/not Continuous | 0 | 0.25 | 0.00 | BW14 - Insufficient Vehicular Separation | 0 | 0.25 | 0.00 |

Condition Score 0.00

Report Date: 3/10/2015 4:40:19 PM Page 11 of 80

Assessment Area Eastmoor / JD Estates

Assessment Sub-Area EJ1

Infrastructure Category Bikeways/Trails

Exhibit Group E.6

| LMI Benefit | | | | | |
|--|-----------------|-------|---------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q46c: Census Block Group | 40027.2021.05.3 | 0.00 | 10.00 | 0.00 | |
| Q47: Improvements to Infrastructure would benefit LMI Census Block Group | No | 0.00 | 5.00 | 0.00 | |
| | | | LMI Score | 0.00 | |

| Health and Safety Weighting | | | | |
|--|-------|-------|-----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q48: Opportunity to harden infrastructure against future disasters | No | 0.00 | 1.00 | 0.00 |
| | | На | alth and Safety Score | 0.00 |

| Long Term Recovery / Economic Revitalizatio | | | Wajakina | | |
|--|-------|-------------------------------|---------------------|-------|--|
| Description | Value | Score | Weighting Factor | Score | |
| Q49: Opportunity to improve community asethetic | No | 0.00 | 5.00 | 0.00 | |
| Q50: Current condition may be deterring reinvestment | Yes | 1.00 | 5.00 | 5.00 | |
| Q51: Historic capacity / load / design issue with infrastructure | Yes | 1.00 | 10.00 | 10.00 | |
| Q52: Projected capacity issue with infrastructure | Yes | 1.00 | 5.00 | 5.00 | |
| Q53: Projected maintenance issue with infrastructure | No | 0.00 | 5.00 | 0.00 | |
| | | Recovery/Revitalization Score | | 20.00 | |

| Sustainability Weighting | | | | |
|--|-------|-------|----------------------|-------|
| Description | Value | Score | Factor | Score |
| Q54: Opportunity for introduction of sustainable design concepts | No | 0.00 | 5.00 | 0.00 |
| | | | Sustainability Score | 0.00 |

| Opportunity Score | | Weighting | | | |
|-----------------------|-------|-----------|-------|--|--|
| Project Description | Score | Factor | Score | | |
| No Projects Available | 0.00 | 0.00 | 0.00 | | |

Infrastructure Photographs







